Register entry, as of 29 October 2026 Listed for sale Record ID ae77e8df2daf

# 2018 Hyundai Santa Fe Sport Sport Value Pkg ,Sport Premium pkg, Sport Tech pkg, Sport 2.0T Base

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5XY | ZUDLB | X | J | G | 516961 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Hyundai · KIA GEORGIA, INC | Santa Fe Sport · 2.4 L | Verified | 2018 | Georgia | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2018 | Engine | 2.4 L, 4 cylinders |
| Make | Hyundai | Fuel | Gasoline |
| Model | Santa Fe Sport | Drive | 4WD |
| Trim | Sport Value Pkg ,Sport Premium pkg, Sport Tech pkg, Sport 2.0T Base | Maker | KIA GEORGIA, INC |
| Body | Sport Utility Vehicle | Plant | Georgia, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/santa-fe-sport/2018

**11** recalls listed by Transport Canada for this model year

### Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

### Brakes

2022616 27 Oct 2022

Issue: On certain vehicles, the control module for the antilock brake system (ABS) could short circuit. Note: This recall doesn't affect vehicles equipped with smart cruise control (SCC). This recall replaces Transport Canada recall 2022-046. Vehicles that were already repaired under Hyundai recall R0208 don't require this repair. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the ABS multi-fuse. Hyundai advises that you may continue to drive your vehicle, however recommends that you should park it outdoors and away from other vehicles or structures until the recall repairs have been completed.

### Brakes

2022046 3 Feb 2022

This recall was replaced by Transport Canada Recall No. 2022-616 due to increase in the number of recalled vehicles. Issue: On certain vehicles, the control module for the antilock brake system (ABS) could short circuit. Note: This recall does not affect vehicles equipped with smart cruise control (SCC). Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the ABS multi-fuse. Hyundai advises that you may continue to drive your vehicle, however recommends that you should park it outdoors and away from other vehicles or structures until the recall repairs have been completed.

### Electrical

2020091 28 Feb 2020

Issue: Certain vehicles may be equipped with an accessory trailer wiring harness kit that could fail. Over time, moisture could enter the control module and cause a short circuit. Note: This recall only affects Hyundai Genuine Accessory trailer wiring harness kits that were manufactured by third parties and sold in Canada. These kits may have been ordered at the time of a vehicle purchase, or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A short circuit could create a fire risk. This risk remains even when the vehicle is parked. Corrective Actions: Hyundai will notify owners by mail and instruct you to inspect your vehicle to see if it has an affected trailer wiring harness installed. If it does, Hyundai will advise you to take your vehicle to a dealer to install a redesigned trailer wiring harness. Hyundai recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.

### Engine

2019640 16 Dec 2019

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This affects Sonata and Santa Fe Sport equipped with a 2.4 L GDI or 2.0 L Turbo GDI engine, as well as Tucson equipped with a 2.4 L GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of an accident. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Vehicles previously repaired under Product Improvement Campaign R0153 (TC # 2019-130) do not require this software update. Owners can find additional information at <a href="http://www.hyundaiengineinfo.ca">www.hyundaiengineinfo.ca</a>.

### Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

5 more on the model-year record, cardog.app/tools/recalls/hyundai/santa-fe-sport/2018

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $13,988[5], $154 under the median of $14,142[4].




| | |
|---|---|
| Lowest ask | $8,499 |
| Middle half | $12,491 – $15,751 |
| Median ask | $14,142 |
| This car | $13,988 |

Same configuration · 18 live listings · as of 29 Oct 2026

### OTHER 2018 HYUNDAI SANTA FE SPORT LISTINGS [5]

| | |
|---|---|
| Scarborough, ON · 180,000 km | $10,999 |
| Mississauga, ON · 210,000 km | $9,888 |
| Brampton, ON · 75,231 km | $13,688 |
| Saint John, NB · 173,433 km | $9,995 |
| Stouffville, ON · 141,077 km | $12,800 |
| Newmarket, ON · 87,013 km | $14,871 |

## §4 EVENTS

| | |
|---|---|
| 2018 | Model year 2018[1]<br>Assembly plant Georgia, United States |
| 8 Jun 2017 | Transport Canada recall 2017298[2]<br>Issued for the model year · Seats and restraints |
| 20 Dec 2017 | Transport Canada recall 2017654[2]<br>Issued for the model year · Airbag |
| 23 Feb 2018 | Transport Canada recall 2018105[2]<br>Issued for the model year · Steering |
| 10 Jan 2019 | Transport Canada recall 2019012[2]<br>Issued for the model year · Engine |
| 11 Mar 2019 | Transport Canada recall 2019130[2]<br>Issued for the model year · Engine |
| 21 Aug 2019 | Transport Canada recall 2019420[2]<br>Issued for the model year · Other |
| 16 Dec 2019 | Transport Canada recall 2019640[2]<br>Issued for the model year · Engine |
| 28 Feb 2020 | Transport Canada recall 2020091[2]<br>Issued for the model year · Electrical |
| 3 Feb 2022 | Transport Canada recall 2022046[2]<br>Issued for the model year · Brakes |
| 27 Oct 2022 | Transport Canada recall 2022616[2]<br>Issued for the model year · Brakes |
| 23 Sep 2024 | Transport Canada recall 2024552[2]<br>Issued for the model year · Label |
| 15 Oct 2026 | Listed for sale, Calgary, AB[5]<br>Crowfoot Hyundai · asking $13,988 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $13,988 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 18 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.