Register entry, as of 27 October 2026 Listed for sale Record ID 6d91263d5230

2020 Toyota Corolla LE

1.8 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5YF	BPRBE	7	L	P	138808
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Corolla · 1.8 L	Verified	2020	Blue Springs	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	1.8 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	Corolla	Drive	4x2
Trim	LE	Maker	TOYOTA MOTOR MANUFACTURING, MISSISSIPPI, INC.
Body	Sedan	Plant	Blue Springs, Mississippi, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/corolla/2020

5 recalls listed by Transport Canada for this model year

Airbag

2023684 20 Dec 2023

Issue: On certain vehicles, a sensor for the occupant classification system (OCS) may not have been manufactured properly. As a result, the sensor could short circuit and cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause a warning message to display on the instrument panel and the airbag indicator light would display "passenger airbag off". Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the OCS sensor.

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Fuel system

2020514 28 Oct 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recalls SRC R95/SRC R96 and SRC RA2/SRC RA3 (Transport Canada Recall Numbers 2020-005 and 2020-088). Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Electrical

2020149 8 Apr 2020

Issue: On certain vehicles, a problem with a connector for the rear hatch wire harness could cause the backup lights to not turn on when the car is reversing. Safety Risk: Backup lights that do not turn on when the vehicle is reversing could increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear hatch wire harness.

Seats and restraints

2019618 11 Dec 2019

Issue: On certain vehicles, the rear seat belts may be assembled incorrectly. As a result, the seat belts may not properly lock-up in certain types of crashes. Safety Risk: A seat belt that does not work properly could increase the risk of injury in a crash. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the rear seat belt assemblies. They will be replaced as necessary.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $21,495[5], $2,507 over the median of $18,988[4].



Lowest ask	$11,999
Middle half	$17,750 – $20,900
Median ask	$18,988
This car	$21,495

Same configuration · 69 live listings · as of 27 Oct 2026

OTHER 2020 TOYOTA COROLLA LISTINGS [5]

Kitchener, ON · 87,999 km	$20,195
Burlington, ON · 129,636 km	$19,498
Richmond Hill, ON · 0 km	$21,360
Sarnia, ON · 114,753 km	$21,888
Levis, QC · 164,494 km	$17,995
Kitchener, ON · 99,879 km	$18,965

§4 EVENTS

2020	Model year 2020[1] Assembly plant Blue Springs, Mississippi, United States
11 Dec 2019	Transport Canada recall 2019618[2] Issued for the model year · Seats and restraints

8 Apr 2020	Transport Canada recall 2020149[2] Issued for the model year · Electrical
28 Oct 2020	Transport Canada recall 2020514[2] Issued for the model year · Fuel system
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
20 Dec 2023	Transport Canada recall 2023684[2] Issued for the model year · Airbag
25 Sep 2026	Listed for sale, Pointe-Aux-Trembles, QC[5] Complexe Kia Montréal · asking $21,495
27 Oct 2026	Listing last updated[5] asking $21,495

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 69 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.