

Register entry, as of 28 October 2026

Listed for sale

Record ID 9383bd02db0f

2022 Tesla Model S

Hatchback · Electric

VEHICLE IDENTIFICATION NUMBER [1]

5YJ SA1E5 5 N F 485616

WMI 1-3

Tesla, Inc.

DESCRIPTOR 4-8

Model S

CHECK 9

Verified

YEAR 10

2022

PLANT 11

Fremont

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	Not in the decode
Make	Tesla	Fuel	Electric
Model	Model S	Drive	Not in the decode
Trim	Not in the decode	Maker	TESLA, INC.
Body	Hatchback	Plant	Fremont, California, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/tesla/model-s/2022

13 recalls listed by Transport Canada for this model year

Visual system

2026221 5 May 2026

Issue: On certain vehicles, a software problem could delay the rearview camera image from displaying when the transmission is shifted into reverse shortly after the vehicle is started. Canadian regulations require the rearview image to display within 2 seconds of shifting the transmission into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Tesla will notify owners by email. Tesla has released an over-the-air software update to fix this problem. There is no further action required if your vehicle has software release 2026.8.6.1 or a later release.

Airbag

2024784 23 Dec 2024

Issue: On certain vehicles, the driver-front airbag may have been damaged during assembly. As a result, the airbag may not inflate properly in a crash. Safety Risk: An airbag that doesn't inflate properly could create an increased risk of injury in a crash. Corrective Actions: Tesla will notify owners by email and advise you to contact Tesla Service to arrange for an inspection and, if necessary, the replacement of the driver-front airbag.

Electrical

2024427 25 Jul 2024

Issue: On certain vehicles, the hood latch assembly could fail and cause the unlatched hood warning not to display on the instrument panel. As a result, you may not be aware that the hood isn't latched properly. If this happens, the hood could open suddenly while driving. Safety Risk: A hood that opens suddenly while driving can block the driver's view and increase the risk of a crash. Corrective Actions: Tesla will notify affected owners by email. Tesla has released an over-the-air software update to fix this issue. There is no further action required if your vehicle has software release 2024.20.3 or a later release.



Seats and restraints

2024298 28 May 2024

Issue: On certain vehicles, the seat belt reminder chime and visual warning may not work when you start the vehicle and your seat belt is not buckled. Canadian regulations require both a seat belt reminder sound and visual telltale when a driver is not wearing their seat belt. Safety Risk: A seat belt warning that doesn't work correctly may not remind you to buckle your seat belt. Not wearing your seat belt can increase the risk of injury in a crash. Corrective Actions: Tesla will notify owners by email and supply an over-the-air software update to activate the seat belt reminder chime and visual warning.

Lights and instruments

2024283 21 May 2024

Issue: A previous over-the-air (OTA) software update could cause the vehicle not to display the correct visual warning indicators when there are problems with the brake system or when the parking brake is applied. As a result, the BRAKE, PARK, and antilock brake system (ABS) visual indicators would display as text instead of symbols. Safety Risk: While there is a low risk to safety, Canadian regulations require visual warnings to use common symbols, instead of words, to avoid driver confusion. Corrective Actions: Tesla will notify affected owners by email. Tesla has released an over-the-air software update to fix this problem. There is no further action required if your vehicle has software release 2024.3.25, 2024.14.5, or a release later than 2024.14.5.

Structure

2023680 19 Dec 2023

Issue: On certain vehicles, a software problem could cause the doors not to stay latched in a crash. As a result, the vehicles may not meet certain side impact protection requirements of Canadian regulations. Safety Risk: A door that opens in a crash could increase the risk of injury. Corrective Actions: Tesla has released an over-the-air software update to fix this problem. There is no further action required if your vehicle has software release 2023.44.30 or a later release. Tesla will notify affected owners by email.

7 more on the model-year record, cardog.app/tools/recalls/tesla/model-s/2022

Listed for the model year, not checked against your VIN. Tesla confirms which apply.
Check your VIN with Tesla or call a Tesla dealer with your VIN.
service.tesla.com/en-CA/vin-recall-search

United States: 20 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$65,520^[5], \$2,928 under the median of \$68,448^[4].



Lowest ask	\$65,520
Middle half	\$67,376 – \$70,424
Median ask	\$68,448
This car	\$65,520

Same model year · 4 live listings · as of 28 Oct 2026

OTHER 2022 TESLA MODEL S LISTINGS ^[5]

Mont-Royal, QC · 28,500 km	\$68,900
Toronto, ON · 46,929 km	\$74,995
Markham, ON · 49,933 km	\$67,995

§4 EVENTS

2022 Model year 2022^[1]
Assembly plant Fremont, California, United States



1 Feb 2022 Transport Canada recall 2022037^[2]
Issued for the model year · Seats and restraints

3 May 2022 Transport Canada recall 2022228^[2]
Issued for the model year · Electrical

20 Sep 2022 Transport Canada recall 2022528^[2]
Issued for the model year · Visual system

14 Feb 2023 Transport Canada recall 2023063^[2]
Issued for the model year · Accessories

14 Jul 2023 Transport Canada recall 2023393^[2]
Issued for the model year · Seats and restraints

3 Nov 2023 Transport Canada recall 2023595^[2]
Issued for the model year · Airbag

12 Dec 2023 Transport Canada recall 2023657^[2]
Issued for the model year · Accessories

19 Dec 2023 Transport Canada recall 2023680^[2]
Issued for the model year · Structure

21 May 2024 Transport Canada recall 2024283^[2]
Issued for the model year · Lights and instruments

28 May 2024 Transport Canada recall 2024298^[2]
Issued for the model year · Seats and restraints

25 Jul 2024 Transport Canada recall 2024427^[2]
Issued for the model year · Electrical

23 Dec 2024 Transport Canada recall 2024784^[2]
Issued for the model year · Airbag

5 May 2026 Transport Canada recall 2026221^[2]
Issued for the model year · Visual system

21 Jun 2026 Listed for sale, Saint-Jean-Sur-Richelieu, QC^[5]
Honda St-Jean · asking \$65,520

27 Oct 2026 Listing last updated^[5]
asking \$65,520

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.



SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 4 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

