Register entry, as of 28 October 2026 Listed for sale Record ID de620bb6bb50

2018 BMW X6 X6 M

4.4 L, 8 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5YM	KW8C5	7	J	0	Y74657
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Bmw Manufacturer Corpor…	X6 · 4.4 L	Verified	2018	United States	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	4.4 L, 8 cylinders
Make	BMW	Fuel	Gasoline
Model	X6	Drive	Not in the decode
Trim	X6 M	Maker	BMW MANUFACTURER CORPORATION / BMW NORTH AMERICA
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/bmw/x6/2018

5 recalls listed by Transport Canada for this model year

Label

2024544 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Structure

2019582 18 Nov 2019

Issue: On certain vehicles, the attachment points for the lower universal anchorage system (for attaching a child seat) could be damaged over time. As a result, a child seat may come loose. Safety Risk: A child seat that is not properly secured could create an increased risk of injury in a crash. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealer to add a reinforcing bracket to the lower anchor bars and the vehicle body.

Wheels

2018496 12 Sep 2018

On certain vehicles, the wheel bolts may not have been properly tightened. This could cause a wheel could become loose and fall off the vehicle, increasing the risk of a crash causing injury and/or damage to property. In addition, the wheel assembly could strike another vehicle, stationary object, or bystander, causing injury and/or property damage. Correction: Dealers will replace the wheel bolts and tighten them to specification.

Suspension

2018353 28 Jun 2018

On certain vehicles, the front left lower control arm pivot bolt may not have been properly hardened during the manufacturing process. This could cause the front left lower control arm pivot bolt to break, which could affect vehicle handling and control, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the front left lower control arm and replace it as necessary.

Suspension

2017568 17 Nov 2017

On certain vehicles, the lower control arm suspension bolts may not have been tightened properly during the manufacturing process. Loose lower control arm suspension bolts could affect vehicle handling, which would increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the lower control arm suspension bolts and tighten them to specification.

> Listed for the model year, not checked against your VIN. BMW confirms which apply.
> Check your VIN with BMW Canada or call a BMW dealer with your VIN.
> crm.bmw.ca/en-CA/VehicleRecall

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $64,888[5], $33,388 over the median of $31,500[4].

Lowest ask	$21,888
Middle half	$24,249 – $43,771
Median ask	$31,500
This car	$64,888

Same model year · 6 live listings · as of 28 Oct 2026

OTHER 2018 BMW X6 LISTINGS [5]

Calgary, AB · 137,435 km	$29,499
Elie, MB · 42,138 km	$33,500
Calgary, AB · 40,500 km	$47,195
Calgary, AB · 40,500 km	$47,195
Calgary, AB · 40,500 km	$47,195
Calgary, AB · 40,500 km	$47,195

§4 EVENTS

2018	Model year 2018[1] Assembly plant United States
17 Nov 2017	Transport Canada recall 2017568[2] Issued for the model year · Suspension
28 Jun 2018	Transport Canada recall 2018353[2] Issued for the model year · Suspension
12 Sep 2018	Transport Canada recall 2018496[2] Issued for the model year · Wheels

18 Nov 2019	Transport Canada recall 2019582[2] Issued for the model year · Structure
15 Aug 2024	Transport Canada recall 2024544[2] Issued for the model year · Label
23 Oct 2025	Listed for sale, Thornhill, ON[5] Infiniti Of Willowdale · asking $64,888
26 Oct 2026	Listing last updated[5] asking $64,888

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 6 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.