Register entry, as of 29 October 2026 Listed for sale Record ID fb72d3ec95bf

2023 RIVIAN R1T Adventure

AWD · Pickup · Electric

VEHICLE IDENTIFICATION NUMBER [1]

7FC	TGAAA	5	P	N	018295
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Rivian Automotive Llc	R1T	Computes	2023	Normal	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	Not in the decode
Make	RIVIAN	Fuel	Electric
Model	R1T	Drive	AWD
Trim	Adventure	Maker	RIVIAN AUTOMOTIVE LLC
Body	Pickup	Plant	Normal, Illinois, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/rivian/r1t/2023

4 recalls listed by Transport Canada for this model year

Visual system

2026443 17 Sep 2026

Issue: Under certain conditions, a software problem could cause the rearview camera image to be blocked. Canadian regulations require the rearview image to display while the transmission is in reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Rivian will notify owners by email. Rivian has released an over-the-air software update to fix this problem. There is no further action required if your vehicle has software release 2026.23.0 or a later release.

Seats and restraints

2026009 15 Jan 2026

Issue: On certain vehicles, the second-row outboard seat belt retractor(s) may not have been installed properly. As a result, the seat belts could loosen or detach in a crash. Safety Risk: A seat belt that detaches in a crash could increase the risk of injury. Corrective Actions: To reduce the safety risk, Rivian recommends that you shouldn't transport passengers in the second-row outboard seats until the recall repairs are completed. Rivian will notify owners by email and advise you to take your vehicle to a Rivian service center to inspect and, if necessary, secure the seat belt retractor(s).

Suspension

2026002 5 Jan 2026

Issue: On certain vehicles, the rear suspension toe link(s) may not have been properly reinstalled after service. As a result, the toe link(s) could become loose or separate. If this happens, there could be reduced vehicle stability. Safety Risk: Reduced vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: Rivian will notify owners by email and advise you to take your vehicle to a Rivian service center to inspect and, if necessary, replace the rear suspension toe link bolt(s).

Lights and instruments

2024292 24 May 2024

Issue: On certain vehicles, the headlamps may not be aimed correctly. As a result, the vehicles may not meet certain requirements of Canadian regulations. Safety Risk: Headlamps that aren't properly aimed can reduce visibility and could increase the risk of a crash. Corrective Actions: Rivian will notify owners by mail and advise you to bring your vehicle to a Rivian service center to inspect and, if necessary, adjust the headlamps.

> Listed for the model year, not checked against your VIN. RIVIAN confirms which apply.
> No online lookup from RIVIAN · call a RIVIAN dealer with your VIN.

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $88,995[5], $947 under the median of $89,942[4].

Lowest ask	$88,995
Middle half	$89,468 – $90,415
Median ask	$89,942
This car	$88,995

Same model year · 2 live listings · as of 29 Oct 2026

OTHER 2023 RIVIAN R1T LISTINGS [5]

Vancouver, BC · 61,866 km	$90,888

§4 EVENTS

2023	Model year 2023[1] Assembly plant Normal, Illinois, United States
24 May 2024	Transport Canada recall 2024292[2] Issued for the model year · Lights and instruments
5 Jan 2026	Transport Canada recall 2026002[2] Issued for the model year · Suspension
15 Jan 2026	Transport Canada recall 2026009[2] Issued for the model year · Seats and restraints
17 Sep 2026	Transport Canada recall 2026443[2] Issued for the model year · Visual system
28 Oct 2026	Listed for sale, Port Coquitlam, BC[5] TriCity Mitsubishi · asking $88,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 2 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.