Register entry, as of 27 October 2026 Listed for sale Record ID 32c4379b0d12

2020 Volvo S60 Momentum

2.0 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

7JR	102FK	4	L	G	072759
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Volvo Car Usa, Llc	S60 · 2.0 L	Computes	2020	South Carolina	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	2.0 L, 4 cylinders
Make	Volvo	Fuel	Gasoline
Model	S60	Drive	Not in the decode
Trim	Momentum	Maker	VOLVO CAR USA, LLC
Body	Sedan	Plant	South Carolina, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volvo/s60/2020

7 recalls listed by Transport Canada for this model year

High voltage

2025147 20 Mar 2025

Issue: On certain vehicles, there could be a problem inside the high-voltage battery. As a result, the battery modules could overheat and short circuit. Note: This recall only affects certain plug-in hybrid (PHEV) models. Safety Risk: A short circuit in the high-voltage battery can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: To reduce the safety risk, Volvo advises not to charge your vehicle until the recall repairs have been completed. Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the high-voltage battery module(s). The dealer will also install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the affected high-voltage battery module(s).

Brakes

2024628 23 Oct 2024

Issue: On certain vehicles, the rods connecting the brake pedal to the hydraulic brake unit may not have been assembled properly. As a result, the rods could loosen, and you may experience a change in brake pedal feel. This can cause reduced braking. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the brake pedal pushrod screw.

Airbag

2023620 21 Nov 2023

Issue: On certain vehicles, the bolts that attach the front-passenger airbag may not have been properly tightened. As a result, the airbag may not inflate properly in a crash. Safety Risk: An airbag that does not work properly could create an increased risk of injury in a crash. Corrective Actions: Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the front-passenger airbag bolts.

Visual system

2022595 20 Oct 2022

Issue: On certain vehicles, a software problem could cause the top-view camera to display instead of the rearview camera image when you are reversing. Canadian regulations require the rearview image to display when reversing. Note: This recall only affects vehicles equipped with a 360-degree park assist camera. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volvo will notify owners in writing and send a wireless over-the-air update to each vehicle. If the update cannot be completed successfully, or for vehicles without over-the-air (OTA) update capability, Volvo will instruct you to schedule an appointment to have the update performed by a dealer.

Electrical

2021345 2 Jun 2021

Issue: On certain vehicles, the fuse for the low-pressure fuel pump may be too small. As a result, the fuse could blow and the engine could stall while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Action: Volvo will contact owners by mail and instruct you to take your vehicle to a dealer to replace the 15 A fuse for the low-pressure fuel pump with a 20 A fuse.

Seats and restraints

2020298 30 Jun 2020

Issue: On certain vehicles, the flexible steel cable that attaches the seat belt to the outside of the front seats may weaken over time. As a result, the seat belt could detach. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Action: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front-outboard seat belt anchors.

1 more on the model-year record, cardog.app/tools/recalls/volvo/s60/2020

> Listed for the model year, not checked against your VIN. Volvo confirms which apply.
> Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.
> www.volvocars.com/en-ca/l/recall-information/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $23,997[5], the median[4].

Lowest ask	$21,799
Middle half	$23,997 – $29,888
Median ask	$23,997
This car	$23,997

Same model year · 5 live listings · as of 27 Oct 2026

OTHER 2020 VOLVO S60 LISTINGS [5]

Ottawa, ON · 96,729 km	$23,997
Laval, QC · 83,000 km	$20,999
Brampton, ON · 34,500 km	$29,999
Brampton, ON · 52,500 km	$30,000
Oakville, ON · 67,103 km	$29,888

§4 EVENTS

2020 **Model year 2020**[1]
Assembly plant South Carolina, United States

13 Mar 2020	Transport Canada recall 2020099[2] Issued for the model year · Brakes
30 Jun 2020	Transport Canada recall 2020298[2] Issued for the model year · Seats and restraints
2 Jun 2021	Transport Canada recall 2021345[2] Issued for the model year · Electrical
20 Oct 2022	Transport Canada recall 2022595[2] Issued for the model year · Visual system
21 Nov 2023	Transport Canada recall 2023620[2] Issued for the model year · Airbag
23 Oct 2024	Transport Canada recall 2024628[2] Issued for the model year · Brakes
20 Mar 2025	Transport Canada recall 2025147[2] Issued for the model year · High voltage
18 Sep 2025	Listed for sale, Ottawa, ON[5] Car-On Auto Sales · asking $23,997
27 Oct 2026	Listing last updated[5] asking $23,997

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 5 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.