Register entry, as of 28 October 2026 Listed for sale Record ID 7c9193f52955

# 2022 Volvo S60 R-Design

2.0 L, 4 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 7JR | L12TM | X | N | G | 186831 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Volvo Car Usa, Llc | S60 · 2.0 L | Computes | 2022 | South Carolina | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | 2.0 L, 4 cylinders |
| Make | Volvo | Fuel | Gasoline |
| Model | S60 | Drive | AWD |
| Trim | R-Design | Maker | VOLVO CAR USA, LLC |
| Body | Sedan | Plant | South Carolina, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volvo/s60/2022

**4** recalls listed by Transport Canada for this model year

### High voltage

2025147 20 Mar 2025

Issue: On certain vehicles, there could be a problem inside the high-voltage battery. As a result, the battery modules could overheat and short circuit. Note: This recall only affects certain plug-in hybrid (PHEV) models. Safety Risk: A short circuit in the high-voltage battery can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: To reduce the safety risk, Volvo advises not to charge your vehicle until the recall repairs have been completed. Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the high-voltage battery module(s). The dealer will also install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the affected high-voltage battery module(s).

### Airbag

2023620 21 Nov 2023

Issue: On certain vehicles, the bolts that attach the front-passenger airbag may not have been properly tightened. As a result, the airbag may not inflate properly in a crash. Safety Risk: An airbag that does not work properly could create an increased risk of injury in a crash. Corrective Actions: Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the front-passenger airbag bolts.

### Visual system

2022595 20 Oct 2022

Issue: On certain vehicles, a software problem could cause the top-view camera to display instead of the rearview camera image when you are reversing. Canadian regulations require the rearview image to display when reversing. Note: This recall only affects vehicles equipped with a 360-degree park assist camera. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volvo will notify owners in writing and send a wireless over-the-air update to each vehicle. If the update cannot be completed successfully, or for vehicles without over-the-air (OTA) update capability, Volvo will instruct you to schedule an appointment to have the update performed by a dealer.

### Seats and restraints

2021540 1 Sep 2021

Issue: On certain vehicles, the passenger seat belt assemblies may contain defective automatic locking retractors (ALR). As a result, the seat belts may not properly lock to secure a child seat. Note: The vehicle's lower universal anchorage system (UAS) is not affected by this defect and may still be used to secure a child seat. Safety Risk: A seat belt that is used to secure a child restraint but is not properly locked could increase the risk of injury in a crash. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the seat belts. They will be replaced, if necessary.

> Listed for the model year, not checked against your VIN. Volvo confirms which apply.
> Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.
> www.volvocars.com/en-ca/l/recall-information/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $37,995[5], the median[4].

| | |
|---|---|
| Lowest ask | $29,900 |
| Middle half | $33,446 – $40,995 |
| Median ask | $37,995 |
| This car | $37,995 |

Same model year · 7 live listings · as of 27 Oct 2026

OTHER 2022 VOLVO S60 LISTINGS [5]

| | |
|---|---|
| Fredericton, NB · 59,605 km | $32,994 |
| Hamilton, ON · 17,033 km | $40,995 |
| Montréal, QC · 80,245 km | $29,900 |
| Vaughan, ON · 57,243 km | $33,898 |

## §4 EVENTS

| | |
|---|---|
| 2022 | Model year 2022[1]<br>Assembly plant South Carolina, United States |
| 1 Sep 2021 | Transport Canada recall 2021540[2]<br>Issued for the model year · Seats and restraints |
| 20 Oct 2022 | Transport Canada recall 2022595[2]<br>Issued for the model year · Visual system |
| 21 Nov 2023 | Transport Canada recall 2023620[2]<br>Issued for the model year · Airbag |
| 20 Mar 2025 | Transport Canada recall 2025147[2]<br>Issued for the model year · High voltage |
| 12 Aug 2026 | Listed for sale, Brossard, QC[5]<br>Park Avenue BMW Brossard · asking $37,995 |

| | |
|---|---|
| 25 Oct 2026 | Listing last updated[5]<br>asking $37,995 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 7 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.