Register entry, as of 28 October 2026 Listed for sale Record ID 4455cbfc1ad6

2023 Toyota Corolla Cross LE

2.0 L, 4 cylinders · 4x2 · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

7MU	CAABG	4	P	V	065523
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Mazda Toyota Manufacturi…	Corolla Cross · 2.0 L	Computes	2023	Huntsville	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	2.0 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	Corolla Cross	Drive	4x2
Trim	LE	Maker	MAZDA TOYOTA MANUFACTURING, USA, INC.
Body	Sport Utility Vehicle	Plant	Huntsville, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/corolla-cross/2023

5 recalls listed by Transport Canada for this model year

Airbag

2025242 6 May 2025

Issue: On certain vehicles, the steering wheel spiral cable assembly could disconnect. If this happens, the airbag (SRS) warning lamp would turn on, and the driver-front airbag wouldn't work in a crash. This may also cause the horn or other steering wheel-mounted controls not to work properly. Note: This recall replaces Transport Canada recall no. 2023-386. Vehicles that were repaired under that recall don't require this repair. Safety Risk: An airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect the production date of the spiral cable assembly, and replace it if necessary.

Airbag

2025037 29 Jan 2025

Issue: On certain vehicles, the inspection completed by a Toyota dealer during recall SRC RF2 (Transport Canada recall no. 2023-386) may not have been done correctly. As a result, a second inspection is required. On certain vehicles, the steering wheel spiral cable assembly could disconnect. If this happens, the airbag (SRS) warning lamp would turn on, and the driver-front airbag wouldn't work in a crash. This may also cause the horn or other steering wheel-mounted controls not to work properly. Safety Risk: An airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect the production date of the spiral cable assembly, and replace it if necessary.

Airbag

2023681 20 Dec 2023

Issue: On certain vehicles, the inspection completed by a Toyota dealer during recall SRC RF0 (Transport Canada recall 2023-311) may not address the safety risk. As a result, a second inspection is required. On certain vehicles, a problem with the instrument panel could cause the passenger-front airbag not to open and inflate properly in a crash. Safety Risk: An airbag that doesn't inflate properly could create an increased risk of injury in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the instrument panel. To reduce the safety risk, Toyota recommends not to transport a person in the front-passenger seat until the recall repairs have been completed.

Airbag

2023386 12 Jul 2023

This recall was replaced by Transport Canada recall no. 2025-242. Issue: On certain vehicles, the steering wheel spiral cable assembly could disconnect. If this happens, the airbag (SRS) warning lamp would turn on, and the driver-front airbag wouldn't work in a crash. This may also cause the horn or other steering wheel-mounted controls not to work properly. Safety Risk: An airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect the production date of the spiral cable assembly, and replace it if necessary.

Airbag

2023311 30 May 2023

Issue: On certain vehicles, a problem with the instrument panel could cause the passenger-front airbag not to open and inflate properly in a crash. Safety Risk: An airbag that doesn't inflate properly could create an increased risk of injury in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the instrument panel. To reduce the safety risk, Toyota recommends not to transport a person in the front-passenger seat until the recall repairs have been completed.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $26,850[5], $2,392 under the median of $29,242[4].

Lowest ask	$24,995
Middle half	$27,920 – $31,071
Median ask	$29,242
This car	$26,850

Same configuration · 16 live listings · as of 28 Oct 2026

OTHER 2023 TOYOTA COROLLA CROSS LISTINGS [5]

Milton, ON · 40,402 km	$33,499
Cobourg, ON · 53,852 km	$28,988
Toronto, ON · 37,629 km	$27,500
Laval, QC · 38,376 km	$28,995
Laval, QC · 137,409 km	$24,295
Drummondville, QC · 78,284 km	$27,729

§4 EVENTS

2023	Model year 2023[1] Assembly plant Huntsville, Alabama, United States
30 May 2023	Transport Canada recall 2023311[2] Issued for the model year · Airbag
12 Jul 2023	Transport Canada recall 2023386[2] Issued for the model year · Airbag
20 Dec 2023	Transport Canada recall 2023681[2] Issued for the model year · Airbag
29 Jan 2025	Transport Canada recall 2025037[2] Issued for the model year · Airbag
6 May 2025	Transport Canada recall 2025242[2] Issued for the model year · Airbag
25 Oct 2026	Listed for sale, Toronto, ON[5] Autorama · asking $26,850
28 Oct 2026	Listing last updated[5] asking $26,850

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 16 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.