

Register entry, as of 26 October 2026

Listed for sale Record ID 6e4be2bdafe0

2024 Tesla Model Y

Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER ^[1]

7SA YGDEF 1 R F 016874

WMI 1-3 Tesla, Inc.	DESCRIPTOR 4-8 Model Y	CHECK 9 Computes	YEAR 10 2024	PLANT 11 Fremont	SERIAL 12-17 Build sequence
------------------------	---------------------------	---------------------	-----------------	---------------------	--------------------------------

§1 IDENTITY ^[1]

Model year	2024	Engine	Not in the decode
Make	Tesla	Fuel	Electric
Model	Model Y	Drive	Not in the decode
Trim	Not in the decode	Maker	TESLA, INC.
Body	Sport Utility Vehicle	Plant	Fremont, California, United States

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/tesla/model-y/2024

3 recalls listed by Transport Canada for this model year

Visual system 2025002 7 Jan 2025

Issue: On certain vehicles, a software problem could cause the computer circuit board to short circuit. If this happens, the rearview camera image may not display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Tesla has released an over-the-air software update to fix this problem. Tesla will notify owners by email. Tesla will also identify vehicles in which the computer circuit board experienced a short circuit, or damage that could lead to a short circuit, prior to the release of software versions 2024.44.25.3, 2024.45.25.6 or a later release. If your vehicle is identified, you will be advised to contact Tesla Service to replace the car computer.

Electrical 2024427 25 Jul 2024

Issue: On certain vehicles, the hood latch assembly could fail and cause the unlatched hood warning not to display on the instrument panel. As a result, you may not be aware that the hood isn't latched properly. If this happens, the hood could open suddenly while driving. Safety Risk: A hood that opens suddenly while driving can block the driver's view and increase the risk of a crash. Corrective Actions: Tesla will notify affected owners by email. Tesla has released an over-the-air software update to fix this issue. There is no further action required if your vehicle has software release 2024.20.3 or a later release.

Lights and instruments

2024283 21 May 2024

Issue: A previous over-the-air (OTA) software update could cause the vehicle not to display the correct visual warning indicators when there are problems with the brake system or when the parking brake is applied. As a result, the BRAKE, PARK, and antilock brake system (ABS) visual indicators would display as text instead of symbols. Safety Risk: While there is a low risk to safety, Canadian regulations require visual warnings to use common symbols, instead of words, to avoid driver confusion. Corrective Actions: Tesla will notify affected owners by email. Tesla has released an over-the-air software update to fix this problem. There is no further action required if your vehicle has software release 2024.3.25, 2024.14.5, or a release later than 2024.14.5.

Listed for the model year, not checked against your VIN. Tesla confirms which apply.
Check your VIN with Tesla or call a Tesla dealer with your VIN.

service.tesla.com/en-CA/vin-recall-search

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$55,995^[5], \$6,248 over the median of \$49,747^[4].



Lowest ask	\$33,995
Middle half	\$43,492 – \$53,440
Median ask	\$49,747
This car	\$55,995

Same model year · 22 live listings · as of 26 Oct 2026

OTHER 2024 TESLA MODEL Y LISTINGS [5]

Newmarket, ON · 43,482 km	\$55,999
Barrie, ON · 50,395 km	\$52,879
Thornhill, ON · 87,000 km	\$49,999
Hamilton, ON · 61,631 km	\$54,998
Hamilton, ON · 13,395 km	\$58,498
Barrie, ON · 104,424 km	\$47,218

§4 EVENTS

2024	Model year 2024 ^[1] Assembly plant Fremont, California, United States
21 May 2024	Transport Canada recall 2024283 ^[2] Issued for the model year · Lights and instruments
25 Jul 2024	Transport Canada recall 2024427 ^[2] Issued for the model year · Electrical
7 Jan 2025	Transport Canada recall 2025002 ^[2] Issued for the model year · Visual system
25 Oct 2026	Listed for sale, Vancouver, BC ^[5] Kingsway Honda · asking \$55,995



26 Oct 2026 Listing last updated^[5]
asking \$55,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 22 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 26 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

