

Register entry, as of 28 October 2026

Listed for sale

Record ID 5855da187b32

2010 Mitsubishi Lancer

2.0 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JA3 **2U2FU** **2** **A** **U** **600952**

WMI 1-3

Mitsubishi Motors Corporat...

DESCRIPTOR 4-8

Lancer · 2.0 L

CHECK 9

Computes

YEAR 10

2010

PLANT 11

Mizushima

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	2.0 L, 4 cylinders
Make	Mitsubishi	Fuel	Gasoline
Model	Lancer	Drive	4x2
Trim	Not in the decode	Maker	Mitsubishi Motors Corporation (MMC)
Body	Sedan	Plant	Mizushima, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mitsubishi/lancer/2010

8 recalls listed by Transport Canada for this model year

Structure	2020216	15 May 2020
Issue: On certain vehicles, road salt can corrode the front cross-member (subframe). As a result, a lower control arm could eventually detach from the cross-member. This could cause a loss of vehicle control. Safety Risk: A loss of control can create the risk of a crash. Corrective Actions: Mitsubishi will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the front cross-member (subframe). If no significant corrosion is found, the dealer will spray a sealing and anti-corrosion coating both inside and on the cross-member. If significant corrosion is found, the dealer will replace the cross-member.		
Visual system	2018588	26 Oct 2018
On certain vehicles, water may drain from the windshield cowl area onto the front wiper link ball joint. Over time, this could result in corrosion and/or wear to the joint, which could result in the separation of the wiper link ball. If separation were to occur, the windshield wipers could become inoperative, which could limit the driver's visibility under certain operating conditions which may increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the wiper link rod with a countermeasure one, and will replace the wiper motor crank arm with a new one.		
Accessories	2018054	26 Jan 2018
On certain vehicles, the sunroof may not have been bonded properly and could separate from the vehicle. This could pose a risk to other road users, increasing the risk of injury and/or damage to property. Correction: Dealers will replace the sunroof glass assembly.		



Electrical

2018052 26 Jan 2018

On certain vehicles, the flange of the drive belt automatic tensioner may crack over time due to repetitive high load operations and stress concentration. This could cause the drive belt to detach, leading to battery depletion, which would result in a loss of motive power and a loss of power steering assist. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the auto tensioner with a countermeasure unit.

Airbag

2016382 29 Jul 2016

On certain vehicles operated in areas of heavy road salt usage, a mixture of snow, water and road-salt solution may infiltrate between the front impact sensor and the bracket that attaches it to the vehicle. Over time, repeated freezing/thawing cycles could cause a crack to develop in the sensor case allowing water intrusion and short circuit of the sensor. In the event of a crash, this could result in delayed deployment of the driver and passenger front airbags which would increase the risk of injury. Correction: Dealers will inspect the front impact sensor and replace it if it is found to be cracked. An updated designed bracket and cover will also be installed.

Heater and defroster

2015166 17 Apr 2015

On certain vehicles, the blower motor may have been incorrectly manufactured. This could result in a premature failure of the blower motor which could affect the defroster performance resulting in reduced visibility, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace blower motor and the power transistor as needed.

2 more on the model-year record, cardog.app/tools/recalls/mitsubishi/lancer/2010

Listed for the model year, not checked against your VIN. Mitsubishi confirms which apply.
Check your VIN with Mitsubishi Canada or call a Mitsubishi dealer with your VIN.
www.mitsubishi-motors.ca/en/owners/maintenance-service/mitsubishi-recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$7,450^[5], \$3,455 over the median of \$3,995^[4].



Lowest ask	\$3,491
Middle half	\$3,743 – \$5,722
Median ask	\$3,995
This car	\$7,450

Same model year · 3 live listings · as of 28 Oct 2026

OTHER 2010 MITSUBISHI LANCER LISTINGS ^[5]

Candiac, QC · 227,401 km	\$3,491
Vaudreuil-Dorion, QC · 227,401 km	\$3,491
Vaudreuil-Dorion, QC · 227,401 km	\$3,491
Laval, QC · 227,401 km	\$3,491
Toronto, ON · 264,350 km	\$3,995
Brossard, QC · 227,401 km	\$3,491

§4 EVENTS

2010

Model year 2010^[1]

Assembly plant Mizushima, Japan



15 Sep 2014	Transport Canada recall 2014397 ^[2] Issued for the model year · Engine
17 Apr 2015	Transport Canada recall 2015166 ^[2] Issued for the model year · Heater and defroster
17 Apr 2015	Transport Canada recall 2015165 ^[2] Issued for the model year · Lights and instruments
29 Jul 2016	Transport Canada recall 2016382 ^[2] Issued for the model year · Airbag
26 Jan 2018	Transport Canada recall 2018054 ^[2] Issued for the model year · Accessories
26 Jan 2018	Transport Canada recall 2018052 ^[2] Issued for the model year · Electrical
26 Oct 2018	Transport Canada recall 2018588 ^[2] Issued for the model year · Visual system
15 May 2020	Transport Canada recall 2020216 ^[2] Issued for the model year · Structure
21 May 2026	Listed for sale, Calgary, AB ^[5] Sam Motors · asking \$7,450
27 Oct 2026	Listing last updated ^[5] asking \$7,450

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 3 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

