

Register entry, as of 27 October 2026

Listed for sale

Record ID 5d00d28f3d77

2015 Mitsubishi Lancer

2.0 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JA3 **2U2FU** **5** **F** **U** **602993**

WMI 1-3

Mitsubishi Motors Corporat...

DESCRIPTOR 4-8

Lancer · 2.0 L

CHECK 9

Computes

YEAR 10

2015

PLANT 11

Mizushima

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.0 L, 4 cylinders
Make	Mitsubishi	Fuel	Gasoline
Model	Lancer	Drive	4x2
Trim	Not in the decode	Maker	Mitsubishi Motors Corporation (MMC)
Body	Sedan	Plant	Mizushima, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mitsubishi/lancer/2015

4 recalls listed by Transport Canada for this model year

Visual system 2018588 26 Oct 2018

On certain vehicles, water may drain from the windshield cowl area onto the front wiper link ball joint. Over time, this could result in corrosion and/or wear to the joint, which could result in the separation of the wiper link ball. If separation were to occur, the windshield wipers could become inoperative, which could limit the driver's visibility under certain operating conditions which may increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the wiper link rod with a countermeasure one, and will replace the wiper motor crank arm with a new one.

Engine 2017475 29 Sep 2017

On certain vehicles, defective electrical relays may have been installed in the power distribution center. This could cause various electrical circuits to fail, potentially resulting in engine stalling, reduced engine power, or loss of engine cooling fan function potentially resulting in engine overheating. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace affected relay(s) with updated parts.

Airbag 2016382 29 Jul 2016

On certain vehicles operated in areas of heavy road salt usage, a mixture of snow, water and road-salt solution may infiltrate between the front impact sensor and the bracket that attaches it to the vehicle. Over time, repeated freezing/thawing cycles could cause a crack to develop in the sensor case allowing water intrusion and short circuit of the sensor. In the event of a crash, this could result in delayed deployment of the driver and passenger front airbags which would increase the risk of injury. Correction: Dealers will inspect the front impact sensor and replace it if it is found to be cracked. An updated designed bracket and cover will also be installed.



Powertrain

2016379 27 Jul 2016


On certain vehicles equipped with a continuously variable transmission (CVT), the range switch could momentarily experience a loss of signal. If this occurs, the driver may experience an unexpected reduction of vehicle acceleration which could, in conjunction with traffic, road conditions and the driver's reactions, increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will reprogram the CVT-ECU.

Listed for the model year, not checked against your VIN. Mitsubishi confirms which apply.
Check your VIN with Mitsubishi Canada or call a Mitsubishi dealer with your VIN.
www.mitsubishi-motors.ca/en/owners/maintenance-service/mitsubishi-recalls

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$9,450^[5], the median^[4].



Lowest ask	\$6,998
Middle half	\$7,992 – \$11,992
Median ask	\$9,450
This car	\$9,450

Same model year · 7 live listings · as of 27 Oct 2026

OTHER 2015 MITSUBISHI LANCER LISTINGS ^[5]

Vaudreuil-Dorion, QC · 137,000 km	\$7,990
Quebec, QC · 155,319 km	\$7,495
Sainte-Rose, QC · 149,453 km	\$7,995
Calgary, AB · 140,684 km	\$10,990
Oakville, ON · 115,400 km	\$14,988
Mount Hope, Hamilton, ON · 67,629 km	\$49,998

§4 EVENTS

2015	Model year 2015 ^[1] Assembly plant Mizushima, Japan
27 Jul 2016	Transport Canada recall 2016379 ^[2] Issued for the model year · Powertrain
29 Jul 2016	Transport Canada recall 2016382 ^[2] Issued for the model year · Airbag
29 Sep 2017	Transport Canada recall 2017475 ^[2] Issued for the model year · Engine
26 Oct 2018	Transport Canada recall 2018588 ^[2] Issued for the model year · Visual system



24 Jul 2026 Listed for sale, Calgary, AB^[5]
Sam Motors · asking \$9,450

26 Oct 2026 Listing last updated^[5]
asking \$9,450

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 7 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

