

Register entry, as of 26 October 2026

Listed for sale

Record ID 5a2c33e0f34a

2012 Mitsubishi Lancer Evolution

2.0 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JA3 **2W5FV** **3** **C** **U** **611269**

WMI 1-3

Mitsubishi Motors Corporat...

DESCRIPTOR 4-8

Lancer Evolution · 2.0 L

CHECK 9

Computes

YEAR 10

2012

PLANT 11

Mizushima

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2012	Engine	2.0 L, 4 cylinders
Make	Mitsubishi	Fuel	Gasoline
Model	Lancer Evolution	Drive	Not in the decode
Trim	Not in the decode	Maker	Mitsubishi Motors Corporation (MMC)
Body	Sedan	Plant	Mizushima, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mitsubishi/lancer-evolution/2012

4 recalls listed by Transport Canada for this model year

Visual system 2018588 26 Oct 2018

On certain vehicles, water may drain from the windshield cowl area onto the front wiper link ball joint. Over time, this could result in corrosion and/or wear to the joint, which could result in the separation of the wiper link ball. If separation were to occur, the windshield wipers could become inoperative, which could limit the driver's visibility under certain operating conditions which may increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the wiper link rod with a countermeasure one, and will replace the wiper motor crank arm with a new one.

Airbag 2016382 29 Jul 2016

On certain vehicles operated in areas of heavy road salt usage, a mixture of snow, water and road-salt solution may infiltrate between the front impact sensor and the bracket that attaches it to the vehicle. Over time, repeated freezing/thawing cycles could cause a crack to develop in the sensor case allowing water intrusion and short circuit of the sensor. In the event of a crash, this could result in delayed deployment of the driver and passenger front airbags which would increase the risk of injury. Correction: Dealers will inspect the front impact sensor and replace it if it is found to be cracked. An updated designed bracket and cover will also be installed.

Powertrain 2013316 20 Sep 2013

On certain vehicles, the clutch master cylinder may fail, resulting in an inability to disengage the clutch or to shift gears. This could result in unintended vehicle movement, increased stopping distances and engine stalling. Such an occurrence could increase the risk of a crash causing injury or property damage. Correction: Dealers will replace the clutch master cylinder.



Lights and instruments

2012001 4 Jan 2012

Certain vehicles fail to comply with the requirements of Canada Motor Vehicle Safety Standard 108 – Lighting System and Retroreflective Devices. An incorrectly manufactured turn signal lever could cause the auto-cancel function to become inoperative. The vehicle operator will, however, continue to be able to manually cancel the turn signals. Correction: Dealers will inspect and, if necessary, replace the turn signal lever.

Listed for the model year, not checked against your VIN. Mitsubishi confirms which apply.
Check your VIN with Mitsubishi Canada or call a Mitsubishi dealer with your VIN.
www.mitsubishi-motors.ca/en/owners/maintenance-service/mitsubishi-recalls

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$20,980^[5], the median^[4].



Lowest ask	\$20,980
Middle half	\$20,980 – \$20,980
Median ask	\$20,980
This car	\$20,980

Same model year · 1 live listings · as of 26 Oct 2026

§4 EVENTS

2012	Model year 2012 ^[1] Assembly plant Mizushima, Japan
4 Jan 2012	Transport Canada recall 2012001 ^[2] Issued for the model year · Lights and instruments
20 Sep 2013	Transport Canada recall 2013316 ^[2] Issued for the model year · Powertrain
29 Jul 2016	Transport Canada recall 2016382 ^[2] Issued for the model year · Airbag
26 Oct 2018	Transport Canada recall 2018588 ^[2] Issued for the model year · Visual system
24 Oct 2026	Listed for sale, Winnipeg, MB ^[5] McWilliam Auto Service · asking \$20,980

§5 DOCUMENTS

Window sticker We have not collected this label yet.



SOURCES

- [1] Cardog identity register, decoded from the VIN
- [2] Transport Canada recall database, listed for the model year
- [3] NHTSA recall records (United States), listed for the model year
- [4] Cardog market quote, same model year, 1 live listings, as of 26 Oct 2026
- [5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

