Register entry, as of 28 October 2026 Listed for sale Record ID 6a0dde6eac93

2016 Mitsubishi Outlander ES (Canada)

2.4 L · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JA4	AZ2A3	2	G	Z	604793
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mitsubishi Motors Corporat…	Outlander · 2.4 L	Computes	2016	Okazaki	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	2.4 L
Make	Mitsubishi	Fuel	Gasoline
Model	Outlander	Drive	4WD
Trim	ES (Canada)	Maker	Mitsubishi Motors Corporation (MMC)
Body	Sport Utility Vehicle	Plant	Okazaki, Aichi, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mitsubishi/outlander/2016

8 recalls listed by Transport Canada for this model year

Structure

2025405 6 Aug 2025

Issue: On certain vehicles, water could enter the tailgate struts and cause them to corrode. If this happens, the struts could fail, and the tailgate could drop suddenly. Safety Risk: A tailgate that drops suddenly could increase the risk of injury. Corrective Actions: Mitsubishi will notify owners by mail and advise you to take your vehicle to a dealership to replace the tailgate struts.

Label

2024554 19 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words and abbreviations listed on the label for "TIRES", "RIMS", "WITH", "FR" and "RR" and appear in English only, when they should be listed as "TIRES/PNEUS", "RIMS/JANTES", "WITH/AVEC", "FR/AVT" and "RR/ARR". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Mitsubishi has corrected the compliance label for all new vehicles.

Brakes

2020579 27 Nov 2020

Issue: On certain vehicles, the parking brake operating shaft in the rear brake caliper could rust and become stuck. If this happens, the parking brake may not work properly. As a result, the brakes could drag or parking brake performance could be reduced. If the vehicle is not left in in gear when it is parked, it could roll away. Note: This is an expansion of recall SR-18-002 (Transport Canada Recall No. 2018-053). Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: Mitsubishi will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear brake calipers.

Seats and restraints

2020317 14 Jul 2020

Issue: On certain vehicles, the seat belt buckle for the right seat in the second-row could be damaged when the seats are folded down. This can cause the seat belt buckle cover to come off. If this happens, the seat belt may not latch properly. Safety Risk: A seat belt that does not latch properly could create an increased risk of injury in a crash. Corrective Actions: Mitsubishi will notify owners by mail and instruct you to take your vehicle to a dealer to modify the center seat belt buckle in the second seating row. A warning label will also be attached to the right seat base and additional instructions will be added to the owner's manual.

Brakes

2018053 26 Jan 2018

On certain vehicles, insufficient rust prevention to the parking brake shaft and insufficient sealing performance of the rear brake caliper boot could allow water to penetrate inside these components causing corrosion. As a result, the parking brake shaft may become stuck causing brake dragging and/or decreased parking brake performance. Additionally, the automatic adjuster for the brake pad clearance of the rear brake caliper with the built-in parking brake may not work correctly. These conditions could lead to a vehicle rollaway, which would increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect and repair the rear brakes as necessary.

Engine

2017475 29 Sep 2017

On certain vehicles, defective electrical relays may have been installed in the power distribution center. This could cause various electrical circuits to fail, potentially resulting in engine stalling, reduced engine power, or loss of engine cooling fan function potentially resulting in engine overheating. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace affected relay(s) with updated parts.

2 more on the model-year record, cardog.app/tools/recalls/mitsubishi/outlander/2016

> Listed for the model year, not checked against your VIN. Mitsubishi confirms which apply.
> Check your VIN with Mitsubishi Canada or call a Mitsubishi dealer with your VIN.
> www.mitsubishi-motors.ca/en/owners/maintenance-service/mitsubishi-recalls

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $9,490[5], $1,660 under the median of $11,150[4].

Lowest ask	$4,999
Middle half	$8,372 – $11,865
Median ask	$11,150
This car	$9,490

Same configuration · 10 live listings · as of 28 Oct 2026

OTHER 2016 MITSUBISHI OUTLANDER LISTINGS [5]

Mcmasterville, QC · 114,647 km	$11,995
Gloucester, ON · 126,690 km	$12,990
Longueuil, QC · 118,900 km	$11,990
Québec, QC · 90,317 km	$13,243
Lethbridge, AB · 171,387 km	$9,995
Barrie, ON · 165,944 km	$10,998

§4 EVENTS

2016	Model year 2016[1] Assembly plant Okazaki, Aichi, Japan
27 Jul 2016	Transport Canada recall 2016379[2] Issued for the model year · Powertrain
7 Apr 2017	Transport Canada recall 2017198[2] Issued for the model year · Structure
29 Sep 2017	Transport Canada recall 2017475[2] Issued for the model year · Engine
26 Jan 2018	Transport Canada recall 2018053[2] Issued for the model year · Brakes
14 Jul 2020	Transport Canada recall 2020317[2] Issued for the model year · Seats and restraints
27 Nov 2020	Transport Canada recall 2020579[2] Issued for the model year · Brakes
19 Sep 2024	Transport Canada recall 2024554[2] Issued for the model year · Label
6 Aug 2025	Transport Canada recall 2025405[2] Issued for the model year · Structure
25 Oct 2026	Listed for sale, Vaudreuil-Dorion, QC[5] Prilo Occasion · asking $9,490
28 Oct 2026	Listing last updated[5] asking $9,490

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 10 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.