Register entry, as of 27 October 2026 Listed for sale Record ID 8a450ec4c3d2

2015 Mitsubishi Outlander ES (Canada)

2.4 L · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JA4	AZ2A3	6	F	Z	600938
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mitsubishi Motors Corporat…	Outlander · 2.4 L	Computes	2015	Okazaki	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.4 L
Make	Mitsubishi	Fuel	Gasoline
Model	Outlander	Drive	4WD
Trim	ES (Canada)	Maker	Mitsubishi Motors Corporation (MMC)
Body	Sport Utility Vehicle	Plant	Okazaki, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mitsubishi/outlander/2015

6 recalls listed by Transport Canada for this model year

Structure — 2025405 — 6 Aug 2025

Issue: On certain vehicles, water could enter the tailgate struts and cause them to corrode. If this happens, the struts could fail, and the tailgate could drop suddenly. Safety Risk: A tailgate that drops suddenly could increase the risk of injury. Corrective Actions: Mitsubishi will notify owners by mail and advise you to take your vehicle to a dealership to replace the tailgate struts.

Label — 2024554 — 19 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words and abbreviations listed on the label for "TIRES", "RIMS", "WITH", "FR" and "RR" and appear in English only, when they should be listed as "TIRES/PNEUS", "RIMS/JANTES", "WITH/AVEC", "FR/AVT" and "RR/ARR". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Mitsubishi has corrected the compliance label for all new vehicles.

Seats and restraints — 2020317 — 14 Jul 2020

Issue: On certain vehicles, the seat belt buckle for the right seat in the second-row could be damaged when the seats are folded down. This can cause the seat belt buckle cover to come off. If this happens, the seat belt may not latch properly. Safety Risk: A seat belt that does not latch properly could create an increased risk of injury in a crash. Corrective Actions: Mitsubishi will notify owners by mail and instruct you to take your vehicle to a dealer to modify the center seat belt buckle in the second seating row. A warning label will also be attached to the right seat base and additional instructions will be added to the owner's manual.

Electrical

2018589 26 Oct 2018

On certain vehicles, a wiring connector located under the driver's side carpet may become contaminated by salt water and corrode over time. This could cause a short-circuit that may cause the connector to overheat and melt and potentially lead to a fire if combustible objects are nearby. A vehicle fire could result in injury and/or damage to property. Correction: Dealers will relocate and replace the wiring connector terminal to a higher position and replace the rear display harness with a new one.

Brakes

2018053 26 Jan 2018

On certain vehicles, insufficient rust prevention to the parking brake shaft and insufficient sealing performance of the rear brake caliper boot could allow water to penetrate inside these components causing corrosion. As a result, the parking brake shaft may become stuck causing brake dragging and/or decreased parking brake performance. Additionally, the automatic adjuster for the brake pad clearance of the rear brake caliper with the built-in parking brake may not work correctly. These conditions could lead to a vehicle rollaway, which would increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect and repair the rear brakes as necessary.

Engine

2017475 29 Sep 2017

On certain vehicles, defective electrical relays may have been installed in the power distribution center. This could cause various electrical circuits to fail, potentially resulting in engine stalling, reduced engine power, or loss of engine cooling fan function potentially resulting in engine overheating. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace affected relay(s) with updated parts.

> Listed for the model year, not checked against your VIN. Mitsubishi confirms which apply.
> Check your VIN with Mitsubishi Canada or call a Mitsubishi dealer with your VIN.
> www.mitsubishi-motors.ca/en/owners/maintenance-service/mitsubishi-recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $7,871[5], $1,727 under the median of $9,598[4].



Lowest ask	$4,990
Middle half	$7,803 – $11,996
Median ask	$9,598
This car	$7,871

Same model year · 12 live listings · as of 27 Oct 2026

OTHER 2015 MITSUBISHI OUTLANDER LISTINGS [5]

Calgary, AB · 91,832 km	$16,799
Ottawa, ON · 196,800 km	$5,999
Boucherville, QC · 165,457 km	$10,695
Montreal, QC · 174,972 km	$7,599
Peterborough, ON · 133,478 km	$11,998
Welland, ON · 197,000 km	$7,999

§4 EVENTS

2015 Model year 2015[1]
Assembly plant Okazaki, Japan

29 Sep 2017	Transport Canada recall 2017475[2] Issued for the model year · Engine
26 Jan 2018	Transport Canada recall 2018053[2] Issued for the model year · Brakes
26 Oct 2018	Transport Canada recall 2018589[2] Issued for the model year · Electrical
14 Jul 2020	Transport Canada recall 2020317[2] Issued for the model year · Seats and restraints
19 Sep 2024	Transport Canada recall 2024554[2] Issued for the model year · Label
6 Aug 2025	Transport Canada recall 2025405[2] Issued for the model year · Structure
25 Oct 2026	Listed for sale, Ottawa, ON[5] DriveTown Ottawa · asking $7,871
27 Oct 2026	Listing last updated[5] asking $7,871

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 12 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.