Register entry, as of 29 October 2026 Listed for sale Record ID 044330f22213

# 2022 Mitsubishi Outlander SEL/SEL Special Edition/GT

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| JA4 | J4VA8 | 1 | N | Z | 612909 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Mitsubishi Motors Corporat… | Outlander · 2.5 L | Computes | 2022 | Okazaki | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | 2.5 L, 4 cylinders |
| Make | Mitsubishi | Fuel | Gasoline |
| Model | Outlander | Drive | 4WD |
| Trim | SEL/SEL Special Edition/GT | Maker | Mitsubishi Motors Corporation (MMC) |
| Body | Sport Utility Vehicle | Plant | Okazaki, Aichi Prefecture, Japan |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/mitsubishi/outlander/2022

**8** recalls listed by Transport Canada for this model year

### Structure

2025405 6 Aug 2025

Issue: On certain vehicles, water could enter the tailgate struts and cause them to corrode. If this happens, the struts could fail, and the tailgate could drop suddenly. Safety Risk: A tailgate that drops suddenly could increase the risk of injury. Corrective Actions: Mitsubishi will notify owners by mail and advise you to take your vehicle to a dealership to replace the tailgate struts.

### Visual system

2025301 30 May 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display screen. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall replaces Transport Canada recall no. 2023-285. Vehicles that were repaired under that recall also require this repair. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mitsubishi will notify owners by mail and advise you to take your vehicle to a dealership to update the infotainment display software.

### Label

2024554 19 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words and abbreviations listed on the label for "TIRES", "RIMS", "WITH", "FR" and "RR" and appear in English only, when they should be listed as "TIRES/PNEUS", "RIMS/JANTES", "WITH/AVEC", "FR/AVT" and "RR/ARR". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Mitsubishi has corrected the compliance label for all new vehicles.

### Visual system

2023285 12 May 2023

This recall was replaced by Transport Canada recall no. 2025-301. Issue: On certain vehicles, a software problem could cause the rearview camera image to not appear on the display screen. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mitsubishi will notify owners by mail and instruct you to take your vehicle to a dealership to update the display software.

### Visual system

2022351 30 Jun 2022

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mitsubishi will notify owners by mail and instruct you to take your vehicle to a dealership to update the infotainment display software.

### Seats and restraints

2022251 13 May 2022

Issue: On certain vehicles, the passenger seat belts may contain defective automatic locking retractors (ALR). As a result, the seat belts may not properly lock to secure a child seat. Note: The vehicle's lower universal anchorage system (UAS) is not affected by this defect and may still be used to secure a child seat. Safety Risk: A seat belt that is used to secure a child restraint but is not properly locked could increase the risk of injury in a crash. Corrective Actions: Mitsubishi will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the seat belts for the front passenger seat and the left and right second row seats. They will be replaced, if necessary.

2 more on the model-year record, cardog.app/tools/recalls/mitsubishi/outlander/2022

> Listed for the model year, not checked against your VIN. Mitsubishi confirms which apply.
> Check your VIN with Mitsubishi Canada or call a Mitsubishi dealer with your VIN.
> www.mitsubishi-motors.ca/en/owners/maintenance-service/mitsubishi-recalls

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $27,998[5], $784 over the median of $27,214[4].

| | |
|---|---|
| Lowest ask | $24,770 |
| Middle half | $26,091 – $27,998 |
| Median ask | $27,214 |
| This car | $27,998 |

Same configuration · 18 live listings · as of 29 Oct 2026

### OTHER 2022 MITSUBISHI OUTLANDER LISTINGS [5]

| | |
|---|---|
| Sundridge, ON · 125,880 km | $22,499 |
| Surrey, BC · 97,701 km | $24,980 |
| Levis, QC · 47,589 km | $27,725 |
| St-Félicien, QC · 62,000 km | $25,995 |
| Brossard, QC · 104,906 km | $22,498 |
| Nanaimo, BC · 83,348 km | $27,995 |

## §4 EVENTS

| | |
|---|---|
| 2022 | Model year 2022[1]<br>Assembly plant Okazaki, Aichi Prefecture, Japan |
| 30 Jul 2021 | Transport Canada recall 2021471[2]<br>Issued for the model year · Seats and restraints |
| 24 Jan 2022 | Transport Canada recall 2022018[2]<br>Issued for the model year · Fuel system |
| 13 May 2022 | Transport Canada recall 2022251[2]<br>Issued for the model year · Seats and restraints |
| 30 Jun 2022 | Transport Canada recall 2022351[2]<br>Issued for the model year · Visual system |
| 12 May 2023 | Transport Canada recall 2023285[2]<br>Issued for the model year · Visual system |
| 19 Sep 2024 | Transport Canada recall 2024554[2]<br>Issued for the model year · Label |
| 30 May 2025 | Transport Canada recall 2025301[2]<br>Issued for the model year · Visual system |
| 6 Aug 2025 | Transport Canada recall 2025405[2]<br>Issued for the model year · Structure |
| 1 Oct 2026 | Listed for sale, Victoria, BC[5]<br>Victoria Mitsubishi · asking $27,998 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $27,998 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 18 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.