Register entry, as of 28 October 2026 Listed for sale Record ID 7b5e3bff3ce0

# 2023 Mitsubishi Outlander SEL, 40th Anniversary, Standard

2.4 L, 4 cylinders · Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

| JA4 | T5VA9 | 7 | P | Z | 621177 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Mitsubishi Motors Corporat… | Outlander · 2.4 L | Computes | 2023 | Okazaki City | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 2.4 L, 4 cylinders |
| Make | Mitsubishi | Fuel | Electric |
| Model | Outlander | Drive | Not in the decode |
| Trim | SEL, 40th Anniversary, Standard | Maker | Mitsubishi Motors Corporation (MMC) |
| Body | Sport Utility Vehicle | Plant | Okazaki City, Aichi Prefecture, Japan |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/mitsubishi/outlander/2023

**4** recalls listed by Transport Canada for this model year

### Visual system

2025301 30 May 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display screen. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall replaces Transport Canada recall no. 2023-285. Vehicles that were repaired under that recall also require this repair. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mitsubishi will notify owners by mail and advise you to take your vehicle to a dealership to update the infotainment display software.

### Label

2024554 19 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words and abbreviations listed on the label for "TIRES", "RIMS", "WITH", "FR" and "RR" and appear in English only, when they should be listed as "TIRES/PNEUS", "RIMS/JANTES", "WITH/AVEC", "FR/AVT" and "RR/ARR". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Mitsubishi has corrected the compliance label for all new vehicles.

### Visual system

2023285 12 May 2023

This recall was replaced by Transport Canada recall no. 2025-301. Issue: On certain vehicles, a software problem could cause the rearview camera image to not appear on the display screen. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mitsubishi will notify owners by mail and instruct you to take your vehicle to a dealership to update the display software.

### Brakes

2023284 12 May 2023

Issue: On certain vehicles, the bolts that attach the rear brake calipers may not have been tightened properly. As a result, the bolts could loosen over time and cause reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Mitsubishi will notify owners by mail and advise you to take your vehicle to a dealership to re-tighten the left and right rear brake caliper bolts.

> Listed for the model year, not checked against your VIN. Mitsubishi confirms which apply.
> Check your VIN with Mitsubishi Canada or call a Mitsubishi dealer with your VIN.
> www.mitsubishi-motors.ca/en/owners/maintenance-service/mitsubishi-recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $36,999[5], $1,299 over the median of $35,700[4].

| | |
|---|---|
| Lowest ask | $26,990 |
| Middle half | $31,991 – $37,240 |
| Median ask | $35,700 |
| This car | $36,999 |

Same configuration · 19 live listings · as of 28 Oct 2026

OTHER 2023 MITSUBISHI OUTLANDER LISTINGS [5]

| | |
|---|---|
| Terrebonne, QC · 26,113 km | $33,995 |
| Victoriaville, QC · 86,141 km | $25,995 |
| Kitchener, ON · 75,120 km | $31,641 |
| Kitchener, ON · 81,591 km | $27,997 |
| Surrey, BC · 52,000 km | $30,885 |
| Saint-Félicien, QC · 14,736 km | $34,495 |

## §4 EVENTS

| | |
|---|---|
| 2023 | Model year 2023[1]<br>Assembly plant Okazaki City, Aichi Prefecture, Japan |
| 12 May 2023 | Transport Canada recall 2023285[2]<br>Issued for the model year · Visual system |
| 12 May 2023 | Transport Canada recall 2023284[2]<br>Issued for the model year · Brakes |

| | |
|---|---|
| 19 Sep 2024 | Transport Canada recall 2024554[2]<br>Issued for the model year · Label |
| 30 May 2025 | Transport Canada recall 2025301[2]<br>Issued for the model year · Visual system |
| 25 Oct 2026 | Listed for sale, Kitchener, ON[5]<br>KW Mitsubishi · asking $36,999 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $36,999 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 19 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.