Register entry, as of 27 October 2026 Listed for sale Record ID 20661cd2504f

2015 Subaru Impreza Premium+All Weather Package

2.0 L, 4 cylinders · Wagon · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JF1	GPAC6	4	F	H	310345
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Subaru Corporation	Impreza · 2.0 L	Computes	2015	Japan	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.0 L, 4 cylinders
Make	Subaru	Fuel	Gasoline
Model	Impreza	Drive	Not in the decode
Trim	Premium+All Weather Package	Maker	SUBARU CORPORATION
Body	Wagon	Plant	Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/impreza/2015

5 recalls listed by Transport Canada for this model year

Lights and instruments

2022394 21 Jul 2022

Issue: Over time, the backup lamp switch could corrode and fail. If this happens, the backup lamps will not turn on when the transmission is shifted into reverse and the shift position will not display. Additionally, for vehicles equipped with a rearview camera, the camera image will not appear on the display in the instrument cluster. Safety Risk: Backup lamps that do not work properly could cause a person not to recognize that the vehicle is backing. A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. These issues could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealership to inspect, and if necessary, replace the backup lamp switch.

Brakes

2019104 1 Mar 2019

Issue: On certain vehicles, the brake lamp switch could fail. This would cause the brake lamps not to turn on when the brakes are applied. Depending on the model, this could cause an inability to shift from park or to start using the push-button ignition. This may also cause problems with the following: anti-lock brake system (ABS), vehicle dynamics control (VDC), and/or Eyesight system. Safety Risk: If the brake lights do not work, a following driver may not to recognize that a vehicle ahead is braking, increasing the risk of crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have the brake lamp switch replaced.

Electrical

2017487 6 Oct 2017

On certain vehicles equipped with a factory installed subwoofer located inside the trunk, luggage in the trunk could come into contact the subwoofer wire and move the wire out of its normal position. This could damage the integrated circuit in the subwoofer amplifier and could create a continuous electrical current, resulting in the subwoofer overheating, and would increase the risk of fire causing injury and/or damage to property. Correction: Dealers will inspect, and repair as necessary.

Accessories

2015249 4 Jun 2015

On certain vehicles, if the driver assist system were to become disabled due to a brake light switch failure, the system could fail to inform the driver that the automatic braking, adaptive cruise control and pre-collision braking systems are disabled. This could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will reprogram the driver assist system.

Accessories

2015206 15 May 2015

On certain vehicles equipped with EyeSight driver assist technology, the French version of the EyeSight Owner's Manual my contain incorrect translations of certain text. If the vehicle were to be operated as described in the mistranslated French text, it could increase the risk of a crash. Correction: Subaru will send corrected French EyeSight manuals directly to affected vehicle owners and additional corrected manuals will be available to all Dealers.

> Listed for the model year, not checked against your VIN. Subaru confirms which apply.
> Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
> www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $12,995[5], $3,000 over the median of $9,995[4].

Lowest ask	$3,750
Middle half	$8,442 – $12,496
Median ask	$9,995
This car	$12,995

Same model year · 11 live listings · as of 27 Oct 2026

OTHER 2015 SUBARU IMPREZA LISTINGS [5]

Laval, QC · 118,800 km	$9,995
Montreal, QC · 169,176 km	$7,900
Ste-Foy, QC · 104,855 km	$10,980
Duncan, BC · 141,042 km	$14,900
Vanier, QC · 104,855 km	$10,980
Oakville, ON · 211,100 km	$8,888

§4 EVENTS

2015	Model year 2015[1] Assembly plant Japan
15 May 2015	Transport Canada recall 2015206[2] Issued for the model year · Accessories

4 Jun 2015	Transport Canada recall 2015249[2] Issued for the model year · Accessories
6 Oct 2017	Transport Canada recall 2017487[2] Issued for the model year · Electrical
1 Mar 2019	Transport Canada recall 2019104[2] Issued for the model year · Brakes
21 Jul 2022	Transport Canada recall 2022394[2] Issued for the model year · Lights and instruments
19 Sep 2026	Listed for sale, Dorval, QC[5] Volkswagen Des Sources (Sub-Prime) · asking $12,995
27 Oct 2026	Listing last updated[5] asking $12,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 11 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.