

Register entry, as of 27 October 2026

Listed for sale

Record ID a7b06e392777

2006 Subaru Forester 2.5XS

2.5 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JF1 SG656 2 6 H 726267

WMI 1-3

Subaru Corporation

DESCRIPTOR 4-8

Forester · 2.5 L

CHECK 9

Computes

YEAR 10

2006

PLANT 11

United States

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2006	Engine	2.5 L, 4 cylinders
Make	Subaru	Fuel	Gasoline
Model	Forester	Drive	AWD
Trim	2.5XS	Maker	SUBARU CORPORATION
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/forester/2006

3 recalls listed by Transport Canada for this model year

Suspension

2011344 19 Sep 2011

On certain vehicles, the front lower control arms could corrode due to exposure to humid environments and road de-icing chemicals. Over time, corrosion could progress causing thinning and perforation of the steel, which could allow the control arm to fracture near the forward pivot attachment to the chassis. Lower control arm failure could result in a loss of vehicle control and a crash causing property damage and/or personal injury. Correction: Dealers will inspect the front lower control arms and, depending on the degree of corrosion exhibited, will either rustproof or replace them.

Airbag

2007033 8 Feb 2007

On certain vehicles, the wiring harness for the airbag occupant detection system in the front passenger seating position might have been pinched during vehicle assembly. Pinching of the wiring harness between the floor cross member and the seat mounting bracket could result in an electrical short which would blow the circuit fuse. If this happens, the passenger airbag would be unable to deploy during a crash, leaving the seat occupant susceptible to increased injuries. Correction: Dealers will inspect and, if required, repair wiring damage.

Electrical

2005344 4 Nov 2005

On certain vehicles, a wire for the Immobilizer Control Module was pinched between the two halves of the ICM security cover. As a result, the engine may not start, or may stall while driving. Correction: Dealers will inspect and, if necessary, repair damaged wiring.

Listed for the model year, not checked against your VIN. Subaru confirms which apply.

Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.


www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091



United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$5,599^[5], the median^[4].



Same model year · 1 live listings · as of 27 Oct 2026

§4 EVENTS

2006	Model year 2006 ^[1] Assembly plant United States
4 Nov 2005	Transport Canada recall 2005344 ^[2] Issued for the model year · Electrical
8 Feb 2007	Transport Canada recall 2007033 ^[2] Issued for the model year · Airbag
19 Sep 2011	Transport Canada recall 2011344 ^[2] Issued for the model year · Suspension
26 Oct 2026	Listed for sale, Kelowna, BC ^[5] Buy Direct Truck Centre · asking \$5,599

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 27 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

