Register entry, as of 29 October 2026 Listed for sale Record ID f335f3e09ca2

2021 Subaru Crosstrek Premium+ES

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JF2	GTAPC	4	M	8	288495
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Subaru Corporation	Crosstrek · 2.0 L	Computes	2021	Japan	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.0 L, 4 cylinders
Make	Subaru	Fuel	Gasoline
Model	Crosstrek	Drive	Not in the decode
Trim	Premium+ES	Maker	SUBARU CORPORATION
Body	Sport Utility Vehicle	Plant	Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/crosstrek/2021

4 recalls listed by Transport Canada for this model year

Label — 2024546 — 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.

Electrical — 2023607 — 9 Nov 2023

Issue: On certain vehicles, water could enter the inhibitor switch and cause it to fail. If this happens, the backup lamps may not turn on and the rearview camera image may not display when backing up. This could also cause the gear selection indicator in the instrument panel not to be displayed. Safety Risk: Backup lamps that don't work could cause others not to recognize when a vehicle is backing up. A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. These issues could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and advise you to take your vehicle to a dealership to replace the inhibitor switch.

Electrical — 2023062 — 14 Feb 2023

Issue: On certain Crosstrek Hybrid models, the harness terminal that supplies low-voltage power from the converter to the 12 V battery could corrode. Over time, the terminal could break and cause the 12 V battery not to charge. If this happens, the vehicle could suddenly lose drive power. Safety Risk: A loss of power may increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealership to replace the converter terminal mounting bracket. The dealer will also inspect the 12 V output terminals. If there is no corrosion, the dealer will install a protective cap on the terminals. If corrosion is found, the dealer will replace the 12 V output harness and terminals.

Other

2022435 5 Aug 2022

Issue: On certain Crosstrek plug-in hybrid electric vehicles (PHEV), the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the tire and loading information label for all new vehicles.

> Listed for the model year, not checked against your VIN. Subaru confirms which apply.
> Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
> www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $21,993[5], $551 over the median of $21,442[4].



Lowest ask	$16,999
Middle half	$20,860 – $23,244
Median ask	$21,442
This car	$21,993

Same configuration · 32 live listings · as of 29 Oct 2026

OTHER 2021 SUBARU CROSSTREK LISTINGS [5]

Boisbriand, QC · 102,124 km	$21,493
Ste-Agathe-les-Monts, QC · 96,887 km	$20,377
Québec, QC · 70,511 km	$24,977
Pembroke, ON · 111,950 km	$22,444
Sundridge, ON · 64,291 km	$25,799
Granby, QC · 117,101 km	$19,995

§4 EVENTS

2021	Model year 2021[1] Assembly plant Japan
5 Aug 2022	Transport Canada recall 2022435[2] Issued for the model year · Other
14 Feb 2023	Transport Canada recall 2023062[2] Issued for the model year · Electrical
9 Nov 2023	Transport Canada recall 2023607[2] Issued for the model year · Electrical
15 Aug 2024	Transport Canada recall 2024546[2] Issued for the model year · Label

28 Oct 2026	Listed for sale, Boisbriand, QC[5] Subaru Rive-Nord · asking $21,993
29 Oct 2026	Listing last updated[5] asking $21,993

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 32 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.