Register entry, as of 29 October 2026 Listed for sale Record ID 528eecd009f0

2015 Subaru Forester 2.5+

2.5 L · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JF2	SJCBC	4	F	H	523922
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Subaru Corporation	Forester · 2.5 L	Computes	2015	Japan	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.5 L
Make	Subaru	Fuel	Gasoline
Model	Forester	Drive	Not in the decode
Trim	2.5+	Maker	SUBARU CORPORATION
Body	Sport Utility Vehicle	Plant	Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/forester/2015

5 recalls listed by Transport Canada for this model year

Label

2024546 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.

Airbag

2019492 4 Oct 2019

Issue: On certain vehicles, the passenger occupant detection system (ODS) may malfunction. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the ODS sensor mat harness. It will be replaced if necessary.

Brakes

2019104 1 Mar 2019

Issue: On certain vehicles, the brake lamp switch could fail. This would cause the brake lamps not to turn on when the brakes are applied. Depending on the model, this could cause an inability to shift from park or to start using the push-button ignition. This may also cause problems with the following: anti-lock brake system (ABS), vehicle dynamics control (VDC), and/or Eyesight system. Safety Risk: If the brake lights do not work, a following driver may not to recognize that a vehicle ahead is braking, increasing the risk of crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have the brake lamp switch replaced.

Engine

2016122 17 Mar 2016

On certain vehicles, a portion of the engine turbocharger air intake duct may crack due to incorrect material being used during production. If the air intake duct were to crack, it could result in the engine developing a rough idle, reduced power and possibly a stall. Engine stalling would result in lost propulsion which, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash causing property damage and/or personal injury. Correction: Dealers will inspect the engine turbocharger air intake duct, and replace as necessary.

Accessories

2015206 15 May 2015

On certain vehicles equipped with EyeSight driver assist technology, the French version of the EyeSight Owner's Manual my contain incorrect translations of certain text. If the vehicle were to be operated as described in the mistranslated French text, it could increase the risk of a crash. Correction: Subaru will send corrected French EyeSight manuals directly to affected vehicle owners and additional corrected manuals will be available to all Dealers.

Listed for the model year, not checked against your VIN. Subaru confirms which apply.
Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $11,899[5], $96 under the median of $11,995[4].

Lowest ask	$3,904
Middle half	$8,075 – $14,298
Median ask	$11,995
This car	$11,899

Same model year · 46 live listings · as of 29 Oct 2026

OTHER 2015 SUBARU FORESTER LISTINGS [5]

Victoria, BC · 101,050 km	$16,985
Boisbriand, QC · 247,532 km	$3,904
Longueuil, QC · 189,500 km	$8,490
Vernon, BC · 153,090 km	$15,595
Sherwood Park, AB · 149,878 km	$17,510
Penticton, BC · 152,014 km	$15,904

§4 EVENTS

2015	Model year 2015[1] Assembly plant Japan
15 May 2015	Transport Canada recall 2015206[2] Issued for the model year · Accessories
17 Mar 2016	Transport Canada recall 2016122[2] Issued for the model year · Engine

1 Mar 2019	Transport Canada recall 2019104[2] Issued for the model year · Brakes
4 Oct 2019	Transport Canada recall 2019492[2] Issued for the model year · Airbag
15 Aug 2024	Transport Canada recall 2024546[2] Issued for the model year · Label
28 Oct 2026	Listed for sale, St-Constant, QC[5] St-Constant Honda · asking $11,899

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 46 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.