Register entry, as of 27 November 2026 Listed for sale Record ID 76df2fb1a3e5

# 2014 Subaru Forester Touring+M/R

2.5 L · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| JF2 | SJHLC | 0 | E | H | 442300 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Subaru Corporation | Forester · 2.5 L | Computes | 2014 | Japan | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2014 | Engine | 2.5 L |
| Make | Subaru | Fuel | Gasoline |
| Model | Forester | Drive | Not in the decode |
| Trim | Touring+M/R | Maker | SUBARU CORPORATION |
| Body | Sport Utility Vehicle | Plant | Japan |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/forester/2014

**4** recalls listed by Transport Canada for this model year

### Label

2024546 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.

### Brakes

2019104 1 Mar 2019

Issue: On certain vehicles, the brake lamp switch could fail. This would cause the brake lamps not to turn on when the brakes are applied. Depending on the model, this could cause an inability to shift from park or to start using the push-button ignition. This may also cause problems with the following: anti-lock brake system (ABS), vehicle dynamics control (VDC), and/or Eyesight system. Safety Risk: If the brake lights do not work, a following driver may not to recognize that a vehicle ahead is braking, increasing the risk of crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have the brake lamp switch replaced.

### Accessories

2015206 15 May 2015

On certain vehicles equipped with EyeSight driver assist technology, the French version of the EyeSight Owner's Manual my contain incorrect translations of certain text. If the vehicle were to be operated as described in the mistranslated French text, it could increase the risk of a crash. Correction: Subaru will send corrected French EyeSight manuals directly to affected vehicle owners and additional corrected manuals will be available to all Dealers.

Other 2013134 24 Apr 2013

On certain vehicles, the floor mats can curl when exposed to heat. A deformed mat could interfere with the driver when shifting his/her foot from one pedal to another. This could cause a delay in brake pedal application, which could increase stopping distance, possibly causing a crash resulting in property damage and/or personal injury. Correction: Dealers will replace the vehicle's four carpeted floor mats.

> Listed for the model year, not checked against your VIN. Subaru confirms which apply.
> Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
> www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $14,995[5], $2,495 over the median of $12,500[4].




| | |
|---|---|
| Lowest ask | $5,995 |
| Middle half | $10,746 – $14,245 |
| Median ask | $12,500 |
| This car | $14,995 |

Same model year · 23 live listings · as of 27 Nov 2026

### OTHER 2014 SUBARU FORESTER LISTINGS [5]

| | |
|---|---|
| Toronto, ON · 115,950 km | $10,500 |
| Melville, SK · 282,155 km | $5,995 |
| Nanaimo, BC · 179,937 km | $12,418 |
| Mission, BC · 126,129 km | $13,488 |
| Pincourt, QC · 113,718 km | $13,650 |
| Langley, BC · 154,626 km | $12,694 |

## §4 EVENTS

| | |
|---|---|
| 2014 | Model year 2014[1]<br>Assembly plant Japan |
| 24 Apr 2013 | Transport Canada recall 2013134[2]<br>Issued for the model year · Other |
| 15 May 2015 | Transport Canada recall 2015206[2]<br>Issued for the model year · Accessories |
| 1 Mar 2019 | Transport Canada recall 2019104[2]<br>Issued for the model year · Brakes |
| 15 Aug 2024 | Transport Canada recall 2024546[2]<br>Issued for the model year · Label |
| 18 Nov 2026 | Listed for sale, Vernon, BC[5]<br>HillTop Subaru · asking $14,995 |

26 Nov 2026 **Listing last updated**[5]
asking $14,995

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 23 live listings, as of 27 Nov 2026
[5] Live public dealer listings on Cardog, as of 27 Nov 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.