

Register entry, as of 26 October 2026

Listed for sale

Record ID d4ae3fb5e0bb

2019 Subaru Forester Prm

2.5 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JF2 SKEDC 2 K H 566526

WMI 1-3

Subaru Corporation

DESCRIPTOR 4-8

Forester · 2.5 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Ota

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.5 L, 4 cylinders
Make	Subaru	Fuel	Gasoline
Model	Forester	Drive	AWD
Trim	Prm	Maker	SUBARU CORPORATION
Body	Sport Utility Vehicle	Plant	Ota, Gunma, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/forester/2019

3 recalls listed by Transport Canada for this model year

Label	2024546 15 Aug 2024
Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.	
Suspension	2021226 15 Apr 2021
Issue: On certain vehicles, the bolts for the rear stabilizer bracket could loosen over time. This may cause a rattling notice from the rear of the vehicle. If you continue to drive with this problem, the bolts could detach. If this happens, vehicle stability could be reduced. Safety Risk: Reduced vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the condition of the bolts on the rear stabilizer bracket, and tighten them, if necessary. If a bolt is missing, the dealer will install a new bolt.	
Engine	2019604 2 Dec 2019
Issue: On certain vehicles, the positive crankcase ventilation (PCV) valve could fail. If you continue to operate the vehicle after this happens, pieces of the PCV valve may enter the engine and cause an engine failure. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to replace the PCV valve. Additionally, the replaced PCV valve will be inspected. If the valve is found to have separated, the separator cover and oil pan will be removed. If the separated parts are not located, the engine short block assembly will be replaced.	



Listed for the model year, not checked against your VIN. Subaru confirms which apply.
Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$25,999^[5], \$4,330 over the median of \$21,669^[4].



Lowest ask	\$12,995
Middle half	\$18,842 – \$24,800
Median ask	\$21,669
This car	\$25,999

Same model year · 46 live listings · as of 26 Oct 2026

OTHER 2019 SUBARU FORESTER LISTINGS ^[5]

Courtenay, BC · 103,578 km	\$24,495
Waterloo, ON · 79,000 km	\$25,495
North York, ON · 119,800 km	\$19,880
Thunder Bay, ON · 49,890 km	\$26,733
Grande Prairie, AB · 126,783 km	\$22,805
Barrie, ON · 104,822 km	\$23,995

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Ota, Gunma, Japan
2 Dec 2019	Transport Canada recall 2019604 ^[2] Issued for the model year · Engine
15 Apr 2021	Transport Canada recall 2021226 ^[2] Issued for the model year · Suspension
15 Aug 2024	Transport Canada recall 2024546 ^[2] Issued for the model year · Label
26 Oct 2026	Listed for sale, North Bay, ON ^[5] Subaru of North Bay · asking \$25,999

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.



SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 46 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 26 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

