

Register entry, as of 29 October 2026

Listed for sale

Record ID da1a7e92e805

# 2019 Subaru Forester Prm+ES+SMART

2.5 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**JF2 SKEGC 1 K H 454716**

WMI 1-3

Subaru Corporation

DESCRIPTOR 4-8

Forester · 2.5 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Ota

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                    |
|------------|-----------------------|--------|--------------------|
| Model year | 2019                  | Engine | 2.5 L, 4 cylinders |
| Make       | Subaru                | Fuel   | Gasoline           |
| Model      | Forester              | Drive  | AWD                |
| Trim       | Prm+ES+SMART          | Maker  | SUBARU CORPORATION |
| Body       | Sport Utility Vehicle | Plant  | Ota, Gunma, Japan  |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/subaru/forester/2019](https://cardog.app/tools/recalls/subaru/forester/2019)

## 3 recalls listed by Transport Canada for this model year

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |         |             |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-------------|
| Label                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | 2024546 | 15 Aug 2024 |
| Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.                                                                                                                           |         |             |
| Suspension                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 2021226 | 15 Apr 2021 |
| Issue: On certain vehicles, the bolts for the rear stabilizer bracket could loosen over time. This may cause a rattling notice from the rear of the vehicle. If you continue to drive with this problem, the bolts could detach. If this happens, vehicle stability could be reduced. Safety Risk: Reduced vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the condition of the bolts on the rear stabilizer bracket, and tighten them, if necessary. If a bolt is missing, the dealer will install a new bolt.                     |         |             |
| Engine                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | 2019604 | 2 Dec 2019  |
| Issue: On certain vehicles, the positive crankcase ventilation (PCV) valve could fail. If you continue to operate the vehicle after this happens, pieces of the PCV valve may enter the engine and cause an engine failure. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to replace the PCV valve. Additionally, the replaced PCV valve will be inspected. If the valve is found to have separated, the separator cover and oil pan will be removed. If the separated parts are not located, the engine short block assembly will be replaced. |         |             |



Listed for the model year, not checked against your VIN. Subaru confirms which apply.  
Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.  
[www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091](http://www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091)

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

### §3 VALUE <sup>[4]</sup>

This car asks \$17,995<sup>[5]</sup>, \$6,500 under the median of \$24,495<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$16,151            |
| Middle half | \$19,495 – \$24,900 |
| Median ask  | \$24,495            |
| This car    | \$17,995            |

Same configuration · 13 live listings · as of 29 Oct 2026

#### OTHER 2019 SUBARU FORESTER LISTINGS <sup>[5]</sup>

|                              |          |
|------------------------------|----------|
| Saint John, NB · 73,332 km   | \$25,991 |
| Antigonish, NS · 73,332 km   | \$25,991 |
| Halifax, NS · 73,332 km      | \$25,991 |
| Toronto, ON · 101,929 km     | \$22,995 |
| Ottawa, ON · 110,507 km      | \$22,827 |
| St-Eustache, QC · 128,733 km | \$16,888 |

### §4 EVENTS

|             |                                                                                                  |
|-------------|--------------------------------------------------------------------------------------------------|
| 2019        | Model year 2019 <sup>[1]</sup><br>Assembly plant Ota, Gunma, Japan                               |
| 2 Dec 2019  | Transport Canada recall 2019604 <sup>[2]</sup><br>Issued for the model year · Engine             |
| 15 Apr 2021 | Transport Canada recall 2021226 <sup>[2]</sup><br>Issued for the model year · Suspension         |
| 15 Aug 2024 | Transport Canada recall 2024546 <sup>[2]</sup><br>Issued for the model year · Label              |
| 7 Oct 2026  | Listed for sale, Pointe-Aux-Trembles, QC <sup>[5]</sup><br>Montréal-Est Toyota · asking \$17,995 |
| 29 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$17,995                                           |

### §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.



---

**SOURCES**

- |                                                                     |                                                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 13 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     |                                                                                  |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026                     |

---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

