Register entry, as of 29 October 2026 Listed for sale Record ID 95e071dfe1f9

2014 Acura RLX Advance

3.5 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JH4	KC1F9	6	E	C	800219
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Acura · HONDA MOTOR C…	RLX · 3.5 L	Computes	2014	Sayama	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	3.5 L, 6 cylinders
Make	Acura	Fuel	Gasoline
Model	RLX	Drive	Not in the decode
Trim	Advance	Maker	HONDA MOTOR CO., LTD.
Body	Sedan	Plant	Sayama, Saitama, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/acura/rlx/2014

5 recalls listed by Transport Canada for this model year

Lights and instruments

2015427 25 Sep 2015

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard 108 - Lighting System and Retro reflective Devices. An incorrect lighting sub-harness was installed for the right side headlight. When the lighting master switch is in the parking light position, there is insufficient lighting output from the right side daytime running light, which fails to meet the requirements of the standard. This could reduce vehicle conspicuity, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will install an updated right side headlight sub-harness. Note: This recall only affects RLX hybrid models.

Brakes

2015201 14 May 2015

On certain vehicles, the Collision Mitigation Braking System (CMBS) could unexpectedly activate while operating the vehicle. In rare cases, the system may interpret certain roadside objects, such as metal fences or metal guardrails, as obstacles and apply emergency braking through the CMBS. If the CMBS applies unexpected emergency braking force during normal operation, it could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the vehicle sofware for the system.

Lights and instruments

2014565 12 Dec 2014

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard 108 - Lighting System and Retroreflective Devices. The aluminum film applied to the inner reflector of the headlight may delaminate, potentially diminishing the output of the headlight. This could cause the vehicle to fail to comply with the requirements of CMVSS 108, and decrease driver visibility, increasing the risk of a crash causing injury and/or property damage. Correction: Dealers will replace the headlights.

Seats and restraints

2014453 15 Oct 2014

On certain vehicles, in temperatures below minus 20° Celsius, the ability of the driver's and front passenger's seatbelt to extend and/or retract may be affected. This would result in a seatbelt that cannot be used properly or as it was intended, and could increase the potential for injury to the seat occupant(s) in a crash. Correction: Dealers will replace the driver's seatbelt and front passenger's seatbelt.

Suspension

2013447 18 Dec 2013

On certain vehicles, rear lower control arm bolts may have been insufficiently tightened at time of assembly and could loosen over time. This could result in the driver experiencing difficulty maintaining steering control over the vehicle, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the bolts and tighten to specification.

> Listed for the model year, not checked against your VIN. Acura confirms which apply.
> Check your VIN with Acura Canada or call a Acura dealer with your VIN.
> www.acura.ca/en/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $8,495[5], $4,754 under the median of $13,249[4].

Lowest ask	$8,495
Middle half	$11,498 – $14,499
Median ask	$13,249
This car	$8,495

Same model year · 4 live listings · as of 29 Oct 2026

OTHER 2014 ACURA RLX LISTINGS [5]

Kitchener, ON · 143,861 km	$15,999
Kitchener, ON · 140,000 km	$13,999
Toronto, ON · 119,961 km	$12,499

§4 EVENTS

2014	Model year 2014[1] Assembly plant Sayama, Saitama, Japan
18 Dec 2013	Transport Canada recall 2013447[2] Issued for the model year · Suspension
15 Oct 2014	Transport Canada recall 2014453[2] Issued for the model year · Seats and restraints
12 Dec 2014	Transport Canada recall 2014565[2] Issued for the model year · Lights and instruments
14 May 2015	Transport Canada recall 2015201[2] Issued for the model year · Brakes

25 Sep 2015	Transport Canada recall 2015427[2] Issued for the model year · Lights and instruments
25 Oct 2026	Listed for sale, Komoka, ON[5] Cars in Lobo · asking $8,495
29 Oct 2026	Listing last updated[5] asking $8,495

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 4 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.