

Register entry, as of 27 October 2026

Listed for sale

Record ID f1970618853d

2014 Acura RLX Advance

3.5 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JH4 **KC1F9** **9** **E** **C** **800103**

WMI 1-3

Acura · HONDA MOTOR C...

DESCRIPTOR 4-8

RLX · 3.5 L

CHECK 9

Computes

YEAR 10

2014

PLANT 11

Sayama

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	3.5 L, 6 cylinders
Make	Acura	Fuel	Gasoline
Model	RLX	Drive	Not in the decode
Trim	Advance	Maker	HONDA MOTOR CO., LTD.
Body	Sedan	Plant	Sayama, Saitama, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/acura/rlx/2014

5 recalls listed by Transport Canada for this model year

Lights and instruments

2015427 25 Sep 2015

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard 108 - Lighting System and Retro reflective Devices. An incorrect lighting sub-harness was installed for the right side headlight. When the lighting master switch is in the parking light position, there is insufficient lighting output from the right side daytime running light, which fails to meet the requirements of the standard. This could reduce vehicle conspicuity, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will install an updated right side headlight sub-harness. Note: This recall only affects RLX hybrid models.

Brakes

2015201 14 May 2015

On certain vehicles, the Collision Mitigation Braking System (CMBS) could unexpectedly activate while operating the vehicle. In rare cases, the system may interpret certain roadside objects, such as metal fences or metal guardrails, as obstacles and apply emergency braking through the CMBS. If the CMBS applies unexpected emergency braking force during normal operation, it could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the vehicle software for the system.

Lights and instruments

2014565 12 Dec 2014

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard 108 - Lighting System and Retroreflective Devices. The aluminum film applied to the inner reflector of the headlight may delaminate, potentially diminishing the output of the headlight. This could cause the vehicle to fail to comply with the requirements of CMVSS 108, and decrease driver visibility, increasing the risk of a crash causing injury and/or property damage. Correction: Dealers will replace the headlights.



Seats and restraints

2014453 15 Oct 2014

On certain vehicles, in temperatures below minus 20° Celsius, the ability of the driver's and front passenger's seatbelt to extend and/or retract may be affected. This would result in a seatbelt that cannot be used properly or as it was intended, and could increase the potential for injury to the seat occupant(s) in a crash. Correction: Dealers will replace the driver's seatbelt and front passenger's seatbelt.

Suspension

2013447 18 Dec 2013

On certain vehicles, rear lower control arm bolts may have been insufficiently tightened at time of assembly and could loosen over time. This could result in the driver experiencing difficulty maintaining steering control over the vehicle, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the bolts and tighten to specification.

Listed for the model year, not checked against your VIN. Acura confirms which apply.

Check your VIN with Acura Canada or call a Acura dealer with your VIN.

www.acura.ca/en/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$13,999^[5], \$750 over the median of \$13,249^[4].



Lowest ask	\$8,495
Middle half	\$11,498 – \$14,499
Median ask	\$13,249
This car	\$13,999

Same model year · 4 live listings · as of 27 Oct 2026

OTHER 2014 ACURA RLX LISTINGS [5]

Kitchener, ON · 143,861 km	\$15,999
Komoka, ON · 215,199 km	\$8,495
Toronto, ON · 119,961 km	\$12,499

§4 EVENTS

2014	Model year 2014 ^[1] Assembly plant Sayama, Saitama, Japan
18 Dec 2013	Transport Canada recall 2013447 ^[2] Issued for the model year · Suspension
15 Oct 2014	Transport Canada recall 2014453 ^[2] Issued for the model year · Seats and restraints
12 Dec 2014	Transport Canada recall 2014565 ^[2] Issued for the model year · Lights and instruments
14 May 2015	Transport Canada recall 2015201 ^[2] Issued for the model year · Brakes



25 Sep 2015 Transport Canada recall 2015427^[2]
Issued for the model year · Lights and instruments

25 Oct 2026 Listed for sale, Kitchener, ON^[5]
Auto Expo Inc. · asking \$13,999

27 Oct 2026 Listing last updated^[5]
asking \$13,999

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 4 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

