

Register entry, as of 29 October 2026

Listed for sale

Record ID e6290d3aaf4e

2006 Honda CR-V LX

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JHL RD785 2 6 C 801270

WMI 1-3

Honda Motor Co., Ltd.

DESCRIPTOR 4-8

CR-V · 2.4 L

CHECK 9

Computes

YEAR 10

2006

PLANT 11

Sayama

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2006	Engine	2.4 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	CR-V	Drive	4WD
Trim	LX	Maker	HONDA MOTOR CO., LTD.
Body	Sport Utility Vehicle	Plant	Sayama, Saitama, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/cr-v/2006

5 recalls listed by Transport Canada for this model year

Airbag

2019117 7 Mar 2019

Issue: On certain vehicles, there could be a problem with the driver-front airbag inflator. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, pieces could be propelled toward the occupants. This could also cause damage to the airbag assembly and prevent it from inflating properly. Note: This recall only affects certain vehicles that had a Takata airbag inflator installed during a previous airbag recall or collision repair. Safety Risk: In a crash where the airbag deploys, there could be an increased risk of injury. Corrective Action: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have the driver-front airbag inflator replaced.

Airbag

2017009 10 Jan 2017

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag inflator. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.



Airbag

2015225 27 May 2015

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Note: This recall supersedes special service campaign 2014567. Correction: Dealers will inspect/replace the driver's frontal airbag inflator. All vehicles having received a replacement inflator as part of any previous driver's inflator campaign will have a replacement inflator installed. Note: Honda Canada has created a special Airbag Inflator Hotline for immediate assistance. For more information, please contact: For Honda Owners: 1-877-445-7754 For Acura Owners: 1-877-445-9844

Airbag

2014567 15 Dec 2014

Honda Canada is conducting a voluntary Safety Improvement Campaign concerning the driver's airbag inflator on certain vehicles equipped with Takata airbags. Honda will replace the driver's inflator on affected vehicles. This action is not being conducted under the requirements of the Motor Vehicle Safety Act. Note: This special service campaign was replaced by recall 2015225. Please see recall 2015225 for more information: <http://wwwapps.tc.gc.ca/Saf-Sec-Sur/7/VRDB-BDRV/search-recherche/detail.aspx?lang=eng&&rn=2015225> Click here for more information

Electrical

2011330 7 Sep 2011

On certain vehicles, cleaner residue could infiltrate the master (driver's) power window switch, allowing the switch to overheat and melt. This could result in a vehicle fire causing property damage and/or personal injury. Correction: Dealers will replace the master power window switch with an updated version.

Listed for the model year, not checked against your VIN. Honda confirms which apply.

Check your VIN with Honda Canada or call a Honda dealer with your VIN.

www.honda.ca/en/recalls

United States: 13 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$9,488^[5], the median^[4].



Lowest ask \$9,488

Middle half \$9,488 – \$9,488

Median ask \$9,488

This car \$9,488

Same model year · 1 live listings · as of 29 Oct 2026

§4 EVENTS

2006

Model year 2006^[1]

Assembly plant Sayama, Saitama, Japan

7 Sep 2011

Transport Canada recall 2011330^[2]

Issued for the model year · Electrical

15 Dec 2014

Transport Canada recall 2014567^[2]

Issued for the model year · Airbag



27 May 2015	Transport Canada recall 2015225 ^[2] Issued for the model year · Airbag
10 Jan 2017	Transport Canada recall 2017009 ^[2] Issued for the model year · Airbag
7 Mar 2019	Transport Canada recall 2019117 ^[2] Issued for the model year · Airbag
26 Oct 2026	Listed for sale, Oakville, ON ^[5] CoCars Canada · asking \$9,488
29 Oct 2026	Listing last updated ^[5] asking \$9,488

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

