

Register entry, as of 28 October 2026

Listed for sale

Record ID 829a446e3e28

2019 Honda Clarity PLUG-IN HYBRID TOURING

1.5 L, 4 cylinders · 4x2 · Sedan · Electric

VEHICLE IDENTIFICATION NUMBER ^[1]**JHM ZC5F3 8 K C 800509**

WMI 1-3

Honda Motor Co., Ltd.

DESCRIPTOR 4-8

Clarity · 1.5 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Sayama

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2019	Engine	1.5 L, 4 cylinders
Make	Honda	Fuel	Electric
Model	Clarity	Drive	4x2
Trim	PLUG-IN HYBRID TOURING	Maker	HONDA MOTOR CO., LTD.
Body	Sedan	Plant	Sayama, Saitama, Japan

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/honda/clarity/2019

2 recalls listed by Transport Canada for this model year

Fuel system 2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Fuel system 2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Listed for the model year, not checked against your VIN. Honda confirms which apply.

Check your VIN with Honda Canada or call a Honda dealer with your VIN.

www.honda.ca/en/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]



§3 VALUE [4]

This car asks \$19,495^[5], the median^[4].



Lowest ask	\$18,989
Middle half	\$19,242 – \$19,646
Median ask	\$19,495
This car	\$19,495

Same model year · 3 live listings · as of 28 Oct 2026

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Sayama, Saitama, Japan
18 Dec 2023	Transport Canada recall 2023679 ^[2] Issued for the model year · Fuel system
6 May 2024	Transport Canada recall 2024262 ^[2] Issued for the model year · Fuel system
7 Oct 2026	Listed for sale, Pointe-Claire, QC ^[5] Spinelli Toyota Pointe-Claire · asking \$19,495
28 Oct 2026	Listing last updated ^[5] asking \$19,495

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 3 live listings, as of 28 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 28 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

