

Register entry, as of 28 October 2026

Listed for sale

Record ID 246f55993dec

# 2007 Mazda Mazda3

2.3 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER <sup>[1]</sup>**JM1 BK343 5 7 1 625376**

WMI 1-3

Mazda Motor Corporation

DESCRIPTOR 4-8

Mazda3 · 2.3 L

CHECK 9

Computes

YEAR 10

2007

PLANT 11

Hofu

SERIAL 12-17

Build sequence

## §1 IDENTITY <sup>[1]</sup>

|            |                   |        |                         |
|------------|-------------------|--------|-------------------------|
| Model year | 2007              | Engine | 2.3 L, 4 cylinders      |
| Make       | Mazda             | Fuel   | Gasoline                |
| Model      | Mazda3            | Drive  | Not in the decode       |
| Trim       | Not in the decode | Maker  | Mazda Motor Corporation |
| Body       | Hatchback         | Plant  | Hofu, Yamaguchi, Japan  |

## §2 OBLIGATIONS <sup>[2]</sup>

[cardog.app/tools/recalls/mazda/mazda3/2007](https://cardog.app/tools/recalls/mazda/mazda3/2007)

## 2 recalls listed by Transport Canada for this model year

### Airbag 2021412 2 Jul 2021

Issue: On certain vehicles, the plastic logo on the steering wheel airbag cover could become brittle over time. If this happens, the logo could shatter and could become a projectile when the airbag inflates in a crash. Safety Risk: Loose parts that are projected toward the occupants when an airbag inflates could increase the risk of an injury. Corrective Actions: Mazda will notify owners by mail and instruct you to take your vehicle to a dealer to replace the steering wheel airbag cover.

### Steering 2010274 13 Aug 2010

On certain vehicles with Electro-Hydraulic Power Assist Steering (EHPAS), rust had formed inside the high-pressure pipe on the power steering system during manufacturing due to improper processing. Rust particles may detach from the pipe walls and enter the motorized power steering pump, causing damage to the pump bearings. As a result, gear lubrication may be reduced, leading to an increased load on the motor. Should this happen, there is the potential for the power steering system to enter the fail safe mode in order to prevent overheating, resulting in the power steering warning lamp to light and the motorized pump to stop which could lead to a loss of power assist and the required steering effort will increase. Correction: Dealers will flush the power steering system and repair as necessary.

Listed for the model year, not checked against your VIN. Mazda confirms which apply.

Check your VIN with Mazda Canada or call a Mazda dealer with your VIN.

[www.mazdarecalls.ca/](https://www.mazdarecalls.ca/)

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>



## §3 VALUE [4]

This car asks \$8,930<sup>[5]</sup>, \$5,780 over the median of \$3,150<sup>[4]</sup>.



|             |                   |
|-------------|-------------------|
| Lowest ask  | \$1,495           |
| Middle half | \$2,724 – \$9,464 |
| Median ask  | \$3,150           |
| This car    | \$8,930           |

Same model year · 7 live listings · as of 28 Oct 2026

## OTHER 2007 MAZDA MAZDA3 LISTINGS [5]

|                                 |          |
|---------------------------------|----------|
| 100 Mile House, BC · 260,824 km | \$2,499  |
| Kelowna, BC · 260,824 km        | \$2,499  |
| Victoria, BC · 90,818 km        | \$11,995 |
| Calgary, AB · 193,501 km        | \$9,999  |
| Calgary, AB · 193,501 km        | \$9,999  |
| Calgary, AB · 193,501 km        | \$9,999  |

## §4 EVENTS

|             |                                                                                        |
|-------------|----------------------------------------------------------------------------------------|
| 2007        | Model year 2007 <sup>[1]</sup><br>Assembly plant Hofu, Yamaguchi, Japan                |
| 13 Aug 2010 | Transport Canada recall 2010274 <sup>[2]</sup><br>Issued for the model year · Steering |
| 2 Jul 2021  | Transport Canada recall 2021412 <sup>[2]</sup><br>Issued for the model year · Airbag   |
| 26 Oct 2026 | Listed for sale, Victoria, BC <sup>[5]</sup><br>Malibu Motors · asking \$8,930         |
| 28 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$8,930                                  |

## §5 DOCUMENTS

|                |                                                          |
|----------------|----------------------------------------------------------|
| Window sticker | We do not collect window stickers for this manufacturer. |
|----------------|----------------------------------------------------------|

## SOURCES

|                                                                     |                                                                              |
|---------------------------------------------------------------------|------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 7 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                 |
| [3] NHTSA recall records (United States), listed for the model year |                                                                              |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

