Register entry, as of 27 October 2026 Listed for sale Record ID ce4bd01f00d4

2010 Mazda Mazda3

2.0 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JM1	BL1SF	4	A	1	144671
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mazda Motor Corporation	Mazda3 · 2.0 L	Computes	2010	Hofu	Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	2.0 L, 4 cylinders
Make	Mazda	Fuel	Gasoline
Model	Mazda3	Drive	Not in the decode
Trim	Not in the decode	Maker	Mazda Motor Corporation
Body	Sedan	Plant	Hofu, Yamaguchi, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mazda/mazda3/2010

4 recalls listed by Transport Canada for this model year

Seats and restraints

2017073 13 Feb 2017

On certain vehicles, the push nuts and/or the lifter link which adjusts the height of the driver seat could be of insufficient strength and could become broken or detach from the seat frame. If this occurs, the seat height and inclination position would change rapidly, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the condition of the driver's seat lifter link. If no cracks are detected, a reinforcement bracket will be added to the lifter links, and the number of push nuts will be increased to two per seat lifter link. If any cracks are detected, dealers will replace the entire seat adjuster unit with a modified part.

Structure

2016431 6 Sep 2016

On certain vehicles, the anti-corrosion treatment of the outer tube of the rear lift gate stay may be insufficient. Over time, the outer tube of the rear lift gate stay may corrode and break off, which could increase the risk of injury. Correction: Dealers will replace both rear door stays.

Lights and instruments

2009232 10 Aug 2009

On certain vehicles, a part of the headlight housing where the Daytime Running Light (DRL) bulb is attached may be damage by heat from the bulb when the vehicle is left idling for an extended period or while driving in slow-moving traffic. In the worst case, the housing may be deformed, resulting in bulb becoming detached and loss of DRL functionality. A loss of DRL illumination could render the vehicle less visible to other motorists and to pedestrians during daylight hours, possibly resulting in a crash causing personal injury or death. Correction: Dealers will affect repairs.

Electrical

2009113 16 Apr 2009

On certain vehicles, clearance between the engine harness and the housing of the starter motor may be insufficient. As a result, the covering of the harness may be damaged through vibration during operation, possibly causing a short-circuit between certain harness wires and the starter housing. A short circuit can result in engine control malfunction and/or poor shift quality. In the worst case, the main fuse may blow out causing the engine to stall and inability of restart. Engine stalling would result in lost propulsion which, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash. Correction: Dealers will inspect the engine harness and, if necessary, install a protector clip.

Listed for the model year, not checked against your VIN. Mazda confirms which apply.
Check your VIN with Mazda Canada or call a Mazda dealer with your VIN.
www.mazdarecalls.ca/

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $6,995[5], $3 over the median of $6,992[4].

Lowest ask	$4,567
Middle half	$5,984 – $7,621
Median ask	$6,992
This car	$6,995

Same configuration · 12 live listings · as of 27 Oct 2026

OTHER 2010 MAZDA MAZDA3 LISTINGS [5]

Ottawa, ON · 62,670 km	$6,999
Toronto, ON · 204,007 km	$5,950
Deschaillons-Sur-St-Laurent, QC · 208,000 km	$7,999
Montréal-nord, QC · 196,186 km	$4,567
Lac-Etchemin, QC · 277,000 km	$6,495
Saint-Lin-Laurentides, QC · 187,012 km	$4,495

§4 EVENTS

2010	Model year 2010[1] Assembly plant Hofu, Yamaguchi, Japan
16 Apr 2009	Transport Canada recall 2009113[2] Issued for the model year · Electrical
10 Aug 2009	Transport Canada recall 2009232[2] Issued for the model year · Lights and instruments
6 Sep 2016	Transport Canada recall 2016431[2] Issued for the model year · Structure
13 Feb 2017	Transport Canada recall 2017073[2] Issued for the model year · Seats and restraints

25 Oct 2026	Listed for sale, Vaudreuil-Dorion, QC[5] Prilo Occasion · asking $6,995
27 Oct 2026	Listing last updated[5] asking $6,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 12 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.