

Register entry, as of 26 October 2026

Listed for sale

Record ID 07b8d44c9e9f

# 2018 Mazda Mazda3 Sport

2.0 L, 4 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**JM1** **BN1U7** **3** **J** **1** **170159**

WMI 1-3

Mazda Motor Corporation

DESCRIPTOR 4-8

Mazda3 · 2.0 L

CHECK 9

Computes

YEAR 10

2018

PLANT 11

Hofu

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |        |        |                         |
|------------|--------|--------|-------------------------|
| Model year | 2018   | Engine | 2.0 L, 4 cylinders      |
| Make       | Mazda  | Fuel   | Gasoline                |
| Model      | Mazda3 | Drive  | FWD                     |
| Trim       | Sport  | Maker  | Mazda Motor Corporation |
| Body       | Sedan  | Plant  | Hofu, Yamaguchi, Japan  |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/mazda/mazda3/2018](https://cardog.app/tools/recalls/mazda/mazda3/2018)

## 3 recalls listed by Transport Canada for this model year

### Visual system

2023391 14 Jul 2023

Issue: On certain vehicles, a problem with the rearview camera connector could cause distortion or flickering of the rearview camera image. Note: This recall only affects hatchback (5-door) models. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mazda will notify owners by mail and advise you to take your vehicle to a dealership to inspect the rearview camera and install a seal for the wiring harness. The dealer will replace the rearview camera, if necessary.

### Fuel system

2021696 12 Nov 2021

Issue: On certain vehicles, the fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power while driving could increase the risk of a crash. Corrective Actions: Mazda will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

### Visual system

2019169 4 Apr 2019

Issue: An electrical problem may cause the windshield wipers to stop working. Safety Risk: Windshield wipers that do not work could affect a driver's visibility under certain conditions. This could increase the risk of a crash. Corrective Actions: Mazda will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front body control module with an improved one.

Listed for the model year, not checked against your VIN. Mazda confirms which apply.

Check your VIN with Mazda Canada or call a Mazda dealer with your VIN.

[www.mazdarecalls.ca/](https://www.mazdarecalls.ca/)



United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

### §3 VALUE <sup>[4]</sup>

This car asks \$12,495<sup>[5]</sup>, \$193 under the median of \$12,688<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$7,495             |
| Middle half | \$11,896 – \$14,073 |
| Median ask  | \$12,688            |
| This car    | \$12,495            |

Same configuration · 16 live listings · as of 26 Oct 2026

#### OTHER 2018 MAZDA MAZDA3 LISTINGS <sup>[5]</sup>

|                              |          |
|------------------------------|----------|
| Smiths Falls, ON · 90,579 km | \$18,995 |
| Waterloo, ON · 104,000 km    | \$15,995 |
| Waterloo, ON · 135,000 km    | \$17,495 |
| Lévis, QC · 82,788 km        | \$13,995 |
| Longueuil, QC · 149,077 km   | \$12,955 |
| Québec, QC · 121,223 km      | \$13,999 |

### §4 EVENTS

|             |                                                                                             |
|-------------|---------------------------------------------------------------------------------------------|
| 2018        | Model year 2018 <sup>[1]</sup><br>Assembly plant Hofu, Yamaguchi, Japan                     |
| 4 Apr 2019  | Transport Canada recall 2019169 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 12 Nov 2021 | Transport Canada recall 2021696 <sup>[2]</sup><br>Issued for the model year · Fuel system   |
| 14 Jul 2023 | Transport Canada recall 2023391 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 26 Oct 2026 | Listed for sale, Saint-Sulpice, QC <sup>[5]</sup><br>autosrr.com · asking \$12,495          |

### §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

#### SOURCES

|                                                                     |                                                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 16 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 26 Oct 2026                     |
| [3] NHTSA recall records (United States), listed for the model year |                                                                                  |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

