Register entry, as of 28 October 2026 Listed for sale Record ID b335a49372fd

# 2025 Mazda CX-70 Premium Package

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

| JM3 | KJDHA | X | S | 1 | 134187 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Mazda Motor Corporation | CX-70 · 2.5 L | Computes | 2025 | Hofu | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2025 | Engine | 2.5 L, 4 cylinders |
| Make | Mazda | Fuel | Electric |
| Model | CX-70 | Drive | 4WD |
| Trim | Premium Package | Maker | Mazda Motor Corporation |
| Body | Sport Utility Vehicle | Plant | Hofu, Yamaguchi, Japan |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/mazda/cx-70/2025

**4** recalls listed by Transport Canada for this model year

### Fuel system

2025447 2 Sep 2025

Issue: On certain vehicles, an incorrect fuel level may be displayed on the instrument cluster. As a result, the driver may be unaware of how much fuel is in the tank, and the vehicle could run out of fuel and stall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: To reduce the safety risk, Mazda advises that you should refuel before the fuel gauge reaches ¼ level until the recall repairs have been completed. Mazda will notify owners by mail and advise you to take your vehicle to a dealer to update the body control module software.

### High voltage

2024656 1 Nov 2024

Issue: On certain vehicles, a problem with the inverter software could cause the vehicle to enter a fail-safe mode. If this happens, there could be a loss of power to the wheels. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Mazda will notify owners by mail and advise you to take your vehicle to a dealership to update the inverter software.

### Electrical

2024659 31 Oct 2024

Issue: On certain vehicles, there could be a software problem with the dash electrical supply unit. As a result, the windshield defroster, the seat belt reminder sound and tell-tale, the 360-degree view monitor and high-voltage battery cooling system may not work properly. Safety Risk: A windshield defroster and/or a 360-degree view monitor that doesn't work could cause reduced visibility and increase the risk of a crash. A seat belt warning that doesn't work correctly may not remind you and/or passengers to buckle your seat belt. Not wearing your seat belt can increase the risk of injury in a crash. Corrective Actions: Mazda will notify owners by mail and advise you to take your vehicle to a dealership to update the dash electrical supply unit software.

### Engine

2024657 31 Oct 2024

Issue: On certain vehicles, software problems with the powertrain control module (PCM) and engine control module (ECM) could cause the vehicle to enter a fail-safe mode. If this happens, there could be a loss of power to the wheels. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Mazda will notify owners by mail and advise you to take your vehicle to a dealership to update the PCM and ECM software.

> Listed for the model year, not checked against your VIN. Mazda confirms which apply.
> Check your VIN with Mazda Canada or call a Mazda dealer with your VIN.
> www.mazdarecalls.ca/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $47,997[5], $999 under the median of $48,996[4].

| | |
|---|---|
| Lowest ask | $39,649 |
| Middle half | $45,831 – $65,895 |
| Median ask | $48,996 |
| This car | $47,997 |

Same configuration · 30 live listings · as of 28 Oct 2026

OTHER 2025 MAZDA CX-70 LISTINGS [5]

| | |
|---|---|
| Avonlea, SK · 18,000 km | $49,921 |
| Rouyn-Noranda, QC · 8,672 km | $59,995 |
| Vernon, BC · 44,083 km | $41,577 |
| Brossard, QC · 79,480 km | $39,651 |
| Brossard, QC · 70,524 km | $37,595 |
| Nanaimo, BC · 49,579 km | $42,998 |

## §4 EVENTS

| | |
|---|---|
| 2025 | Model year 2025[1]<br>Assembly plant Hofu, Yamaguchi, Japan |
| 31 Oct 2024 | Transport Canada recall 2024659[2]<br>Issued for the model year · Electrical |
| 31 Oct 2024 | Transport Canada recall 2024657[2]<br>Issued for the model year · Engine |
| 1 Nov 2024 | Transport Canada recall 2024656[2]<br>Issued for the model year · High voltage |
| 2 Sep 2025 | Transport Canada recall 2025447[2]<br>Issued for the model year · Fuel system |

27 Oct 2026 Listed for sale, Dieppe, NB[5]
Atlantic Mazda · asking $47,997

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 30 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.