Register entry, as of 27 October 2026 Listed for sale Record ID bf7fe2b43f28

2016 Infiniti Q50

2.0 L, 4 cylinders · 4WD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JN1	CV7AR	6	G	M	252653
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Infiniti · NISSAN MOTOR C…	Q50 · 2.0 L	Computes	2016	Tochigi Plant	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	2.0 L, 4 cylinders
Make	Infiniti	Fuel	Gasoline
Model	Q50	Drive	4WD
Trim	Not in the decode	Maker	NISSAN MOTOR COMPANY, LTD
Body	Sedan	Plant	Tochigi Plant, Kawachi-Gun, Tochigi, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/infiniti/q50/2016

4 recalls listed by Transport Canada for this model year

Powertrain

2024362 21 Jun 2024

Issue: On certain vehicles, the driveshaft may not have been manufactured properly. As a result, the driveshaft could break and cause a loss of power to the wheels. Additionally, if the vehicle is parked and the parking brake isn't applied, the vehicle could roll away. Note: This recall only affects two-wheel-drive (2WD) models. Safety Risk: A loss of power to the wheels could increase the risk of a crash. A parked vehicle that rolls away could also create the risk of an injury or a crash. Corrective Actions: Nissan will notify owners by mail and advise you to take your vehicle to a dealership to replace the driveshaft.

Fuel system

2017375 27 Jul 2017

On certain vehicles, and incorrect fuel pressure map was used in the Fuel Pump Control Module (FPCM) software as a result, the pressure regulator may fail to open to send fuel from the sub tank to the main tank. Under certain conditions, the fuel level in the main tank could be too low for the fuel pump to send fuel to the engine resulting in a loss of motive power, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the software for the Fuel Pump Control Module.

Steering

2016296 10 Jun 2016

On certain vehicles, a combination of low battery voltage at engine start up (~7 volts) and the vehicle being parked with the wheels turned could cause an error in the Direct Adaptive Steering ECU. This could cause the steering wheel to be off centered and the VDC warning lamp to illuminate. If operated this way, this could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the Direct Adaptive Steering ECU.

Seats and restraints

2016179 25 Apr 2016

On certain vehicles, a defect in the occupant classification system could allow an adult sitting in the front passenger seat to be classified as a child or an “empty seat”. This would suppress the airbag, which could increase the risk of injury in a crash. Correction: For affected Altima, Maxima, Murano, Rogue and Sentra vehicles, dealers will reprogram the airbag control unit and the occupant classification system control unit. For affected Leaf, NV200, Pathfinder, Q50 and JX35/QX60 vehicles, dealers will replace the occupant classification system electronic control unit.

Listed for the model year, not checked against your VIN. Infiniti confirms which apply.
Check your VIN with Infiniti Canada or call a Infiniti dealer with your VIN.
www.infiniti.ca/service/vin-recall.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $13,995[5], $996 over the median of $12,999[4].



Lowest ask	$10,995
Middle half	$12,895 – $14,988
Median ask	$12,999
This car	$13,995

Same model year · 9 live listings · as of 27 Oct 2026

OTHER 2016 INFINITI Q50 LISTINGS [5]

Vaudreuil-Dorion, QC · 152,519 km	$11,270
Carignan, QC · 152,519 km	$11,270
London, ON · 63,000 km	$15,991
Toronto, ON · 161,000 km	$10,995

§4 EVENTS

2016	Model year 2016[1] Assembly plant Tochigi Plant, Kawachi-Gun, Tochigi, Japan
25 Apr 2016	Transport Canada recall 2016179[2] Issued for the model year · Seats and restraints
10 Jun 2016	Transport Canada recall 2016296[2] Issued for the model year · Steering
27 Jul 2017	Transport Canada recall 2017375[2] Issued for the model year · Fuel system
21 Jun 2024	Transport Canada recall 2024362[2] Issued for the model year · Powertrain
12 Oct 2026	Listed for sale, New Minas, NS[5] Bruce Hyundai · asking $13,995

24 Oct 2026	Listing last updated[5] asking $13,995

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 9 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.