Register entry, as of 29 November 2026 Listed for sale Record ID c8aff80acd37

2011 Nissan Juke

1.6 L, 4 cylinders · 4x2 · Crossover Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JN8	AF5MR	1	B	T	006307
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Nissan Motor Company, Ltd	Juke · 1.6 L	Computes	2011	Yokosuka	Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	1.6 L, 4 cylinders
Make	Nissan	Fuel	Gasoline
Model	Juke	Drive	4x2
Trim	Not in the decode	Maker	NISSAN MOTOR COMPANY, LTD
Body	Crossover Utility Vehicle	Plant	Yokosuka, Kanagawa, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/juke/2011

4 recalls listed by Transport Canada for this model year

Fuel system — 2018121 — 8 Mar 2018

On certain vehicles, the fuel pressure sensor may not have been tightened properly when the corrective measure of recall 2012-074 was performed. As a result, the fuel pressure sensor may loosen over time, which could cause a fuel leak. A fuel leak in the presence of an ignition source could result in a fire causing injury and/or damage to property. Correction: Dealers will inspect and retighten the fuel pressure sensor as necessary.

Fuel system — 2014539 — 28 Nov 2014

On certain vehicles, the fuel pressure sensor connected to the engine fuel delivery rail may not have been sufficiently tightened during vehicle assembly. Should the pressure sensor loosen, fuel could leak past a gasket used in the connection between the sensor and the rail. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will inspect the pressure sensor and tighten to specification. Note: This is an expansion of recall 2012-074. Vehicles that were repaired under the previous campaign are not affected because that remedy would have corrected the subject condition.

Fuel system — 2012074 — 23 Feb 2012

On certain vehicles, the fuel pressure sensor connected to the engine fuel delivery rail may not have been sufficiently tightened during vehicle assembly. Should the pressure sensor loosen, fuel could leak past a gasket used in the connection between the sensor and rail. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will inspect for fuel leakage from the pressure sensor and the fuel rail. If there are no signs of a fuel leak, the fuel pressure sensor will be tightened to specifications. If a fuel leak is confirmed, the gasket between the sensor and the fuel delivery rail will be replaced, and the sensor will be tightened.

Engine

2011431 12 Dec 2011

On certain vehicles, a weld at the boost sensor bracket may fail, allowing the bracket to separate from the air inlet tube. If this occurred, the engine would enter fail-safe driving mode, resulting in reduced motive power in which the vehicle could still be driven for short distances. Continued operation could cause the engine to stall which, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash causing property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, replace the air inlet tube assembly.

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $2,900[5], $1,934 under the median of $4,834[4].



Lowest ask	$2,900
Middle half	$4,308 – $5,666
Median ask	$4,834
This car	$2,900

Same model year · 4 live listings · as of 29 Nov 2026

OTHER 2011 NISSAN JUKE LISTINGS [5]

St-Raymond, QC · 161,498 km	$4,777
Peterborough, ON · 69,815 km	$7,995
Coquitlam, BC · 352,500 km	$4,890

§4 EVENTS

2011	Model year 2011[1] Assembly plant Yokosuka, Kanagawa, Japan
12 Dec 2011	Transport Canada recall 2011431[2] Issued for the model year · Engine
23 Feb 2012	Transport Canada recall 2012074[2] Issued for the model year · Fuel system
28 Nov 2014	Transport Canada recall 2014539[2] Issued for the model year · Fuel system
8 Mar 2018	Transport Canada recall 2018121[2] Issued for the model year · Fuel system
14 Nov 2026	Listed for sale, Kelowna, BC[5] Buy Direct Truck Centre · asking $2,900

28 Nov 2026 **Listing last updated**[5]
asking $2,900

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 4 live listings, as of 29 Nov 2026
[5] Live public dealer listings on Cardog, as of 29 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.