Register entry, as of 27 October 2026 Listed for sale Record ID a9f502b66cf3

2012 Nissan Juke

1.6 L, 4 cylinders · 4x2 · Crossover Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JN8	AF5MR	1	C	T	100625
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Nissan Motor Company, Ltd	Juke · 1.6 L	Computes	2012	Yokosuka	Build sequence

§1 IDENTITY [1]

Model year	2012	Engine	1.6 L, 4 cylinders
Make	Nissan	Fuel	Gasoline
Model	Juke	Drive	4x2
Trim	Not in the decode	Maker	NISSAN MOTOR COMPANY, LTD
Body	Crossover Utility Vehicle	Plant	Yokosuka, Kanagawa, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/juke/2012

4 recalls listed by Transport Canada for this model year

Fuel system

2018121 8 Mar 2018

On certain vehicles, the fuel pressure sensor may not have been tightened properly when the corrective measure of recall 2012-074 was performed. As a result, the fuel pressure sensor may loosen over time, which could cause a fuel leak. A fuel leak in the presence of an ignition source could result in a fire causing injury and/or damage to property. Correction: Dealers will inspect and retighten the fuel pressure sensor as necessary.

Fuel system

2014539 28 Nov 2014

On certain vehicles, the fuel pressure sensor connected to the engine fuel delivery rail may not have been sufficiently tightened during vehicle assembly. Should the pressure sensor loosen, fuel could leak past a gasket used in the connection between the sensor and the rail. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will inspect the pressure sensor and tighten to specification. Note: This is an expansion of recall 2012-074. Vehicles that were repaired under the previous campaign are not affected because that remedy would have corrected the subject condition.

Seats and restraints

2012211 12 Jul 2012

On certain vehicles, the rear seat latch strikers (which secure the seat backrest in the upright position) may have been manufactured incorrectly. As a result, the rear seat back strikers may deform during a frontal vehicle crash, which could increase the risk of injury to a rear seat occupant. Correction: Dealers will replace the rear seat latch strikers with updated versions.

Fuel system

2012074 23 Feb 2012

On certain vehicles, the fuel pressure sensor connected to the engine fuel delivery rail may not have been sufficiently tightened during vehicle assembly. Should the pressure sensor loosen, fuel could leak past a gasket used in the connection between the sensor and rail. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will inspect for fuel leakage from the pressure sensor and the fuel rail. If there are no signs of a fuel leak, the fuel pressure sensor will be tightened to specifications. If a fuel leak is confirmed, the gasket between the sensor and the fuel delivery rail will be replaced, and the sensor will be tightened.

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $10,995[5], $2,045 over the median of $8,950[4].



Lowest ask	$6,989
Middle half	$7,970 – $9,972
Median ask	$8,950
This car	$10,995

Same model year · 3 live listings · as of 27 Oct 2026

OTHER 2012 NISSAN JUKE LISTINGS [5]

Surrey, BC · 200,195 km	$8,950
Montréal, QC · 82,496 km	$6,989

§4 EVENTS

2012	Model year 2012[1] Assembly plant Yokosuka, Kanagawa, Japan
23 Feb 2012	Transport Canada recall 2012074[2] Issued for the model year · Fuel system
12 Jul 2012	Transport Canada recall 2012211[2] Issued for the model year · Seats and restraints
28 Nov 2014	Transport Canada recall 2014539[2] Issued for the model year · Fuel system
8 Mar 2018	Transport Canada recall 2018121[2] Issued for the model year · Fuel system
26 Oct 2026	Listed for sale, Steinbach, MB[5] HARVEST HONDA · asking $10,995

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 3 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.