Register entry, as of 25 November 2026 Listed for sale Record ID 343e8508a344

2008 Nissan Rogue

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JN8	AS58V	7	8	W	405748
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Nissan Motor Company, Ltd	Rogue · 2.5 L	Computes	2008	Miyawaka	Build sequence

§1 IDENTITY [1]

Model year	2008	Engine	2.5 L, 4 cylinders
Make	Nissan	Fuel	Gasoline
Model	Rogue	Drive	4WD
Trim	Not in the decode	Maker	NISSAN MOTOR COMPANY, LTD
Body	Sport Utility Vehicle	Plant	Miyawaka, Fukuoka, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/rogue/2008

4 recalls listed by Transport Canada for this model year

Electrical

2015030 26 Jan 2015

On certain vehicles, wiring harness connector could corrode due to exposure to snow/water containing road salt. This could result in an electrical short causing damage to the connector and increasing the risk of a fire causing injury and/or damage to property. Correction: Dealers will add a waterproof seal, inspect the harness connector and replace as necessary.

Steering

2009303 19 Oct 2009

On certain vehicles, the steering gear housing cover screw may have been manufactured out of specification and the axial tension between the screw and gear housing may deteriorate over time. This could allow the screw to gradually loosen, which will cause the steering wheel to exhibit noticeable looseness from the steering assembly. If the vehicle continues to be driven in this condition, the screw may eventually come out of the steering gear housing. If large steering inputs are made with the cover screw missing, the pinion shaft may come out of the steering gear. This may result in a loss of steering control, which could lead to a crash causing property damage, personal injury or death. Correction: Dealers will inspect whether the steering gear cover screw is loose. If it is loose, it will be retightened to the proper specification. In addition, the dealer will install a cover plate to prevent the screw from possibly coming out of the steering gear.

Other

2009283 2 Oct 2009

On certain vehicles, material in the nut used to secure the sensor-transmitter of the Tire Pressure Monitoring System (TPMS) may corrode and crack in areas with heavy concentrations of road salt. If this occurs, the nut may come out of the TPMS sensor-transmitter causing a rapid loss of tire air pressure. This could adversely affect vehicle control and cause a crash resulting in property damage, personal injury or death. Correction: Dealers will replace the TPMS nut with a revised version.

Other 2008363 6 Oct 2008

On certain vehicles, a varistor in the Occupant Classification System (OCS) control unit located in the passenger seat cushion may have been manufactured incorrectly. Under certain conditions, this could cause an interruption of signal between the OCS and the Airbag control unit (ACU). This could result in the passenger airbag being suppressed. The (red) supplemental airbag warning light would flash & the (amber) front passenger airbag status light would illuminate to alert the vehicle operator, however in case of a crash a suppressed airbag could result in personal injury or death. Correction: Dealers will test the signal between the OCS & ACU and if necessary will replace the seat cushion containing OCS hardware.

Listed for the model year, not checked against your VIN. Nissan confirms which apply.
Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
www.nissan.ca/service/vin-recall.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $4,995[5], the median[4].



Lowest ask	$4,950
Middle half	$4,972 – $5,748
Median ask	$4,995
This car	$4,995

Same model year · 3 live listings · as of 25 Nov 2026

OTHER 2008 NISSAN ROGUE LISTINGS [5]

Surrey, BC · 132,058 km	$6,500
Mississauga, ON · 185,111 km	$4,950

§4 EVENTS

2008	Model year 2008[1] Assembly plant Miyawaka, Fukuoka, Japan
6 Oct 2008	Transport Canada recall 2008363[2] Issued for the model year · Other
2 Oct 2009	Transport Canada recall 2009283[2] Issued for the model year · Other
19 Oct 2009	Transport Canada recall 2009303[2] Issued for the model year · Steering
26 Jan 2015	Transport Canada recall 2015030[2] Issued for the model year · Electrical
23 Nov 2026	Listed for sale, Sarnia, ON[5] Lynmar Auto Sales · asking $4,995

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 3 live listings, as of 25 Nov 2026

[5] Live public dealer listings on Cardog, as of 25 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.