Register entry, as of 28 October 2026 Listed for sale Record ID 7aa751c43c6b

2021 Nissan Rogue PLATINUM

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JN8	AT3DD	8	M	W	308924
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Nissan Motor Company, Ltd	Rogue · 2.5 L	Computes	2021	Kyushu Plant	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.5 L, 4 cylinders
Make	Nissan	Fuel	Gasoline
Model	Rogue	Drive	4WD
Trim	PLATINUM	Maker	NISSAN MOTOR COMPANY, LTD
Body	Sport Utility Vehicle	Plant	Kyushu Plant, Miyako-Gun, Fukuoka, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/rogue/2021

9 recalls listed by Transport Canada for this model year

Engine

2025356 27 Jun 2025

Issue: On certain vehicles, the engine may not have been manufactured properly. As a result, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This recall only affects certain vehicles equipped with 1.5 L or 2.0 L variable compression engines. Safety Risk: An engine failure could cause a sudden loss of power to the wheels and/or increase the risk of a vehicle fire. Both issues could increase the risk of a crash or injury. Corrective actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the engine. On certain vehicles, the dealer will also update the engine control module.

Visual system

2022599 21 Oct 2022

Issue: Under certain conditions, a software problem could cause the in-vehicle infotainment system to continuously reboot. If this happens, the rearview camera image will not appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and ask you to make an appointment with your local dealer to update the in-vehicle infotainment system software. For vehicles with over-the-air (OTA) update capability, Nissan will send a wireless over-the-air software update to each vehicle.

Seats and restraints

2022498 2 Sep 2022

Issue: On certain vehicles, the left- and right-rear seat belts may not retract to their storage position. Canadian regulations require seat belts to retract fully when not in use. Safety Risk: A seat belt that doesn't retract properly could be difficult to use. Not wearing a seat belt can increase the risk of injury in a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the left- and right-rear seat belts. They will be replaced, if necessary.

Visual system

2022398 22 Jul 2022

Issue: Under certain conditions, a software problem could cause the in-vehicle infotainment system to reset. If you shift to reverse while the computer is resetting, the rearview camera image will not appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: This recall only affects certain vehicles sold to rental fleets. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and ask you to make an appointment with your local dealer to update the in-vehicle infotainment system software. For vehicles with over-the-air (OTA) update capability, Nissan will send a wireless over-the-air software update to each vehicle.

Lights and instruments

2022153 29 Mar 2022

Issue: On certain vehicles, the automatic headlamps may not turn on soon enough as it gets dark. Canadian regulations require automatic headlamps to turn on when the ambient light level drops below a certain point (1000 lux). Safety Risk: Headlamps that don't turn on as it gets dark could reduce visibility and increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your vehicle to a dealership to reprogram the body control module (BCM).

Fuel system

2021754 10 Dec 2021

Issue: On certain vehicles, the fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power while driving could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

3 more on the model-year record, cardog.app/tools/recalls/nissan/rogue/2021

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $24,800[5], $820 over the median of $23,980[4].



Lowest ask	$18,995
Middle half	$22,244 – $25,888
Median ask	$23,980
This car	$24,800

Same configuration · 31 live listings · as of 28 Oct 2026

OTHER 2021 NISSAN ROGUE LISTINGS [5]

Kitchener, ON · 70,536 km	$22,499
Kingston, ON · 62,685 km	$25,491
Calgary, AB · 47,803 km	$28,851
Ottawa, ON · 89,224 km	$22,495
Edmonton, AB · 125,154 km	$23,980
Westville, NS · 104,300 km	$19,995

§4 EVENTS

2021	Model year 2021[1] Assembly plant Kyushu Plant, Miyako-Gun, Fukuoka, Japan
12 Feb 2021	Transport Canada recall 2021062[2] Issued for the model year · Fuel system
26 Apr 2021	Transport Canada recall 2021245[2] Issued for the model year · Brakes
28 Jun 2021	Transport Canada recall 2021397[2] Issued for the model year · Seats and restraints
10 Dec 2021	Transport Canada recall 2021754[2] Issued for the model year · Fuel system
29 Mar 2022	Transport Canada recall 2022153[2] Issued for the model year · Lights and instruments
22 Jul 2022	Transport Canada recall 2022398[2] Issued for the model year · Visual system
2 Sep 2022	Transport Canada recall 2022498[2] Issued for the model year · Seats and restraints
21 Oct 2022	Transport Canada recall 2022599[2] Issued for the model year · Visual system
27 Jun 2025	Transport Canada recall 2025356[2] Issued for the model year · Engine
25 Oct 2025	Listed for sale, Calgary, AB[5] Happy Corner Auto · asking $24,800
28 Oct 2026	Listing last updated[5] asking $24,800

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 31 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.