Register entry, as of 26 October 2026 Listed for sale Record ID b38b60ed664d

2012 Infiniti QX56

5.6 L, 8 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JN8	AZ2NE	7	C	9	021314
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Infiniti · NISSAN MOTOR C…	QX56 · 5.6 L	Computes	2012	Miyawaka	Build sequence

§1 IDENTITY [1]

Model year	2012	Engine	5.6 L, 8 cylinders
Make	Infiniti	Fuel	Gasoline
Model	QX56	Drive	4WD
Trim	Not in the decode	Maker	NISSAN MOTOR COMPANY, LTD
Body	Sport Utility Vehicle	Plant	Miyawaka, Fukuoka, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/infiniti/qx56/2012

4 recalls listed by Transport Canada for this model year

Label

2026344 15 Jul 2026

Issue: On certain vehicles, the compliance label may list the wrong gross axle weight rating (GAWR) information. This could lead you to overload the vehicle and cause poor handling or a tire failure. Note: This recall only affects models equipped with 22-inch wheels. Safety Risk: Poor handling or a tire failure could cause a loss of vehicle control and result in a crash. Corrective Action: The company will notify owners by mail and provide you with a new compliance label. If you'd like help to install it, you can contact a dealer to have it installed free of charge.

Airbag

2020136 31 Mar 2020

Issue: On certain vehicles, the driver-front airbag inflator could be defective. This could cause the airbag to deploy with more force than normal. It could also cause the inflator to rupture. If the airbag inflator ruptures, fragments could be propelled toward the occupants or cause damage to the airbag and prevent it from inflating properly. Safety Risk: If the vehicle is involved in a crash where the airbag deploys, the airbag inflator could rupture and create a risk of injury or death. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the driver-front airbag inflator or airbag module.

Fuel system

2014539 28 Nov 2014

On certain vehicles, the fuel pressure sensor connected to the engine fuel delivery rail may not have been sufficiently tightened during vehicle assembly. Should the pressure sensor loosen, fuel could leak past a gasket used in the connection between the sensor and the rail. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will inspect the pressure sensor and tighten to specification. Note: This is an expansion of recall 2012-074. Vehicles that were repaired under the previous campaign are not affected because that remedy would have corrected the subject condition.

Fuel system

2012074 23 Feb 2012

On certain vehicles, the fuel pressure sensor connected to the engine fuel delivery rail may not have been sufficiently tightened during vehicle assembly. Should the pressure sensor loosen, fuel could leak past a gasket used in the connection between the sensor and rail. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will inspect for fuel leakage from the pressure sensor and the fuel rail. If there are no signs of a fuel leak, the fuel pressure sensor will be tightened to specifications. If a fuel leak is confirmed, the gasket between the sensor and the fuel delivery rail will be replaced, and the sensor will be tightened.

Listed for the model year, not checked against your VIN. Infiniti confirms which apply.
Check your VIN with Infiniti Canada or call a Infiniti dealer with your VIN.
www.infiniti.ca/service/vin-recall.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $9,995[5], $1,500 under the median of $11,495[4].

Lowest ask	$9,995
Middle half	$10,745 – $12,245
Median ask	$11,495
This car	$9,995

Same model year · 2 live listings · as of 26 Oct 2026

OTHER 2012 INFINITI QX56 LISTINGS [5]

Dawson Creek, BC · 169,327 km	$12,995
Dawson Creek, BC · 169,327 km	$12,995
Hope, BC · 218,079 km	$27,290

§4 EVENTS

2012	Model year 2012[1] Assembly plant Miyawaka, Fukuoka, Japan
23 Feb 2012	Transport Canada recall 2012074[2] Issued for the model year · Fuel system
28 Nov 2014	Transport Canada recall 2014539[2] Issued for the model year · Fuel system
31 Mar 2020	Transport Canada recall 2020136[2] Issued for the model year · Airbag
15 Jul 2026	Transport Canada recall 2026344[2] Issued for the model year · Label
26 Oct 2026	Listed for sale, Toronto, ON[5] Acura Downtown · asking $9,995

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 2 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.