

Register entry, as of 27 October 2026

Listed for sale

Record ID 1092b8040b11

2025 Infiniti QX80 Autograph

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JN8 **AZ3CC** **0** **S** **9** **600117**

WMI 1-3

Infiniti · NISSAN MOTOR C...

DESCRIPTOR 4-8

QX80 · 3.5 L

CHECK 9

Computes

YEAR 10

2025

PLANT 11

Fukuoka

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2025	Engine	3.5 L, 6 cylinders
Make	Infiniti	Fuel	Gasoline
Model	QX80	Drive	4WD
Trim	Autograph	Maker	NISSAN MOTOR COMPANY, LTD
Body	Sport Utility Vehicle	Plant	Fukuoka, Fukuoka, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/infiniti/qx80/2025

4 recalls listed by Transport Canada for this model year

Label	2026344	15 Jul 2026
Issue: On certain vehicles, the compliance label may list the wrong gross axle weight rating (GAWR) information. This could lead you to overload the vehicle and cause poor handling or a tire failure. Note: This recall only affects models equipped with 22-inch wheels. Safety Risk: Poor handling or a tire failure could cause a loss of vehicle control and result in a crash. Corrective Action: The company will notify owners by mail and provide you with a new compliance label. If you'd like help to install it, you can contact a dealer to have it installed free of charge.		
Visual system	2025656	26 Nov 2025
Issue: On certain vehicles, a software problem could cause infotainment system display to remain blank when the vehicle is started. As a result, when the transmission is shifted into reverse gear, the rearview camera image would not appear on the display. Note: This recall only affects certain trim levels. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to update the infotainment system software.		
Visual system	2024592	4 Oct 2024
Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: This problem could cause a "Park Assist is not available" warning message to display. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and advise you to take your vehicle to a dealership to update the around view monitor (AVM) software.		



Visual system

2024590 4 Oct 2024

Issue: On certain vehicles, a software problem with the infotainment system could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: For the Rogue model, this recall only affects the SL and Platinum trim levels. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the infotainment system software. Alternatively, you may schedule an appointment to have the update performed at a Nissan dealership.

Listed for the model year, not checked against your VIN. Infiniti confirms which apply.
Check your VIN with Infiniti Canada or call a Infiniti dealer with your VIN.

www.infiniti.ca/service/vin-recall.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$96,395^[5], \$13,400 over the median of \$82,995^[4].



Lowest ask	\$79,319
Middle half	\$81,834 – \$91,110
Median ask	\$82,995
This car	\$96,395

Same model year · 11 live listings · as of 27 Oct 2026

OTHER 2025 INFINITI QX80 LISTINGS [5]

North Vancouver, BC · 64,286 km	\$79,995
North Vancouver, BC · 64,286 km	\$79,995
Langley, BC · 64,286 km	\$79,995
North Vancouver, BC · 64,286 km	\$79,995
Vancouver, BC · 64,286 km	\$79,995
Vancouver, BC · 64,286 km	\$79,995

§4 EVENTS

2025	Model year 2025 ^[1] Assembly plant Fukuoka, Fukuoka, Japan
4 Oct 2024	Transport Canada recall 2024592 ^[2] Issued for the model year · Visual system
4 Oct 2024	Transport Canada recall 2024590 ^[2] Issued for the model year · Visual system
26 Nov 2025	Transport Canada recall 2025656 ^[2] Issued for the model year · Visual system
15 Jul 2026	Transport Canada recall 2026344 ^[2] Issued for the model year · Label



29 Jul 2026 Listed for sale, Mississauga, ON^[5]
401 Dixie Infiniti · asking \$96,395

27 Oct 2026 Listing last updated^[5]
asking \$96,395

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 11 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

