

Register entry, as of 28 October 2026

Listed for sale      Record ID aa127c2f2ab0

# 2024 Nissan Rogue SV

1.5 L · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JN8

WMI 1-3  
Nissan Motor Company, Ltd

BT3BB

DESCRIPTOR 4-8  
Rogue · 1.5 L

4

CHECK 9  
Computes

R

YEAR 10  
2024

W

PLANT 11  
Japan

441483

SERIAL 12-17  
Build sequence

## §1 IDENTITY [1]

|            |                       |        |                           |
|------------|-----------------------|--------|---------------------------|
| Model year | 2024                  | Engine | 1.5 L                     |
| Make       | Nissan                | Fuel   | Gasoline                  |
| Model      | Rogue                 | Drive  | 4WD                       |
| Trim       | SV                    | Maker  | NISSAN MOTOR COMPANY, LTD |
| Body       | Sport Utility Vehicle | Plant  | Japan                     |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/rogue/2024

### 4 recalls listed by Transport Canada for this model year

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |                        |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|
| Engine                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | 2026056    11 Feb 2026 |
| Issue: On certain vehicles, a software problem could cause the electronic throttle chamber (ETC) to fail. If this happens, there could be a loss of power to the wheels. Note: This recall only affects certain vehicles equipped with 1.5 L variable compression engines. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective actions: Nissan will notify owners by mail and advise you to take your vehicle to a dealership to update the engine control module. The dealer will also inspect and, if necessary, replace the ETC.                                                                                                                                                                                                                          |                        |
| Engine                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | 2026055    11 Feb 2026 |
| Issue: On certain vehicles, the engine may not have been manufactured properly. As a result, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This recall only affects certain vehicles equipped with 1.5 L or 2.0 L variable compression engines. Safety Risk: An engine failure could cause a sudden loss of power to the wheels and/or increase the risk of a vehicle fire. Both issues could increase the risk of a crash or injury. Corrective actions: Nissan will notify owners by mail and advise you to take your vehicle to a dealership to update the engine control module. The dealer will also inspect and, if necessary, replace the engine.                           |                        |
| Engine                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | 2025356    27 Jun 2025 |
| Issue: On certain vehicles, the engine may not have been manufactured properly. As a result, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This recall only affects certain vehicles equipped with 1.5 L or 2.0 L variable compression engines. Safety Risk: An engine failure could cause a sudden loss of power to the wheels and/or increase the risk of a vehicle fire. Both issues could increase the risk of a crash or injury. Corrective actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the engine. On certain vehicles, the dealer will also update the engine control module. |                        |



## Visual system

2024590 4 Oct 2024

Issue: On certain vehicles, a software problem with the infotainment system could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: For the Rogue model, this recall only affects the SL and Platinum trim levels. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the infotainment system software. Alternatively, you may schedule an appointment to have the update performed at a Nissan dealership.

Listed for the model year, not checked against your VIN. Nissan confirms which apply.  
Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.

[www.nissan.ca/service/vin-recall.html](http://www.nissan.ca/service/vin-recall.html)

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

## §3 VALUE [4]

This car asks \$26,999<sup>[5]</sup>, \$201 under the median of \$27,200<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$17,500            |
| Middle half | \$25,995 – \$28,888 |
| Median ask  | \$27,200            |
| This car    | \$26,999            |

Same configuration · 245 live listings · as of 28 Oct 2026

## OTHER 2024 NISSAN ROGUE LISTINGS [5]

|                             |          |
|-----------------------------|----------|
| Woodbridge, ON · 27,878 km  | \$28,495 |
| Calgary, AB · 53,793 km     | \$22,930 |
| Calgary, AB · 36,675 km     | \$20,210 |
| Brantford, ON · 15,279 km   | \$27,999 |
| Mississauga, ON · 21,068 km | \$34,990 |
| Mississauga, ON · 11,041 km | \$34,695 |

## §4 EVENTS

|             |                                                                                             |
|-------------|---------------------------------------------------------------------------------------------|
| 2024        | Model year 2024 <sup>[1]</sup><br>Assembly plant Japan                                      |
| 4 Oct 2024  | Transport Canada recall 2024590 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 27 Jun 2025 | Transport Canada recall 2025356 <sup>[2]</sup><br>Issued for the model year · Engine        |
| 11 Feb 2026 | Transport Canada recall 2026056 <sup>[2]</sup><br>Issued for the model year · Engine        |
| 11 Feb 2026 | Transport Canada recall 2026055 <sup>[2]</sup><br>Issued for the model year · Engine        |



9 Jul 2026      Listed for sale, London, ON<sup>[5]</sup>  
Sport Motors · asking \$26,999

28 Oct 2026      Listing last updated<sup>[5]</sup>  
asking \$26,999

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

- |                                                                     |                                                                                   |
|---------------------------------------------------------------------|-----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 245 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     |                                                                                   |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                      |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

