

Register entry, as of 28 October 2026

Listed for sale

Record ID 934d2944aba0

2008 Infiniti EX35

3.5 L, 6 cylinders · 4WD · Wagon · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JNK **AJ09F** **5** **8** **M** **356259**

WMI 1-3

Infiniti · NISSAN MOTOR C...

DESCRIPTOR 4-8

EX35 · 3.5 L

CHECK 9

Computes

YEAR 10

2008

PLANT 11

Tochigi

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2008	Engine	3.5 L, 6 cylinders
Make	Infiniti	Fuel	Gasoline
Model	EX35	Drive	4WD
Trim	Not in the decode	Maker	NISSAN MOTOR COMPANY, LTD
Body	Wagon	Plant	Tochigi, Kaminokawa, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/infiniti/ex35/2008

4 recalls listed by Transport Canada for this model year

Steering

2015060 11 Feb 2015

On certain vehicles, the steering column upper bearing retainer may fail due to a manufacturing defect. If this occurs, the upper bearing may experience additional stress causing excessive play in the steering wheel. This could result in vehicle instability and increase the risk of injury and/or damage to property. Correction: Dealers will replace steering shaft on EX35/FX35/45 and replace steering column assembly on GT-R.

Lights and instruments

2010383 3 Nov 2010

On certain vehicles, the filament in the bulb of the Daytime Running Lamps (DRL) may burn out due to a shorter lifespan than expected. A loss of DRL illumination could render the vehicle less visible to other motorists and to pedestrians during daylight hours, possibly resulting in a crash causing property damage and/or personal injury. Correction: Dealers will replace the Daytime Running Lamp bulbs with a longer life type bulb.

Other

2008363 6 Oct 2008

On certain vehicles, a varistor in the Occupant Classification System (OCS) control unit located in the passenger seat cushion may have been manufactured incorrectly. Under certain conditions, this could cause an interruption of signal between the OCS and the Airbag control unit (ACU). This could result in the passenger airbag being suppressed. The (red) supplemental airbag warning light would flash & the (amber) front passenger airbag status light would illuminate to alert the vehicle operator, however in case of a crash a suppressed airbag could result in personal injury or death. Correction: Dealers will test the signal between the OCS & ACU and if necessary will replace the seat cushion containing OCS hardware.



Airbag

2008050 13 Feb 2008

If the vehicle battery becomes significantly discharged and the voltage in the electrical system drops (because, for example, the ignition is left in the "ON" position for a significant length of time without the engine running), the Airbag Control unit (ACU) is designed to suppress the passenger airbag and illuminate the passenger airbag status light. When the battery recharges and correct voltage is restored, the ACU is designed to reactivate the passenger airbag system. On certain vehicles, incorrect software programming may not allow the ACU to reactivate the airbag as intended. This can result in the passenger airbag being suppressed without lighting the warning indicator and the airbag status light. Failure of the airbag to inflate during a crash could increase the passenger seat occupant's risk of injury. Correction: Dealers will reprogram the ACU.

Listed for the model year, not checked against your VIN. Infiniti confirms which apply.
Check your VIN with Infiniti Canada or call a Infiniti dealer with your VIN.

www.infiniti.ca/service/vin-recall.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$3,999^[5], \$1,243 under the median of \$5,242^[4].

This car



Lowest ask \$4,990

Middle half \$5,116 – \$5,369

Median ask \$5,242

This car \$3,999

Same model year · 2 live listings · as of 28 Oct 2026

OTHER 2008 INFINITI EX35 LISTINGS ^[5]

Kelowna, BC · 235,565 km	\$5,495
Brantford, ON · 160,410 km	\$4,990

§4 EVENTS

2008	Model year 2008 ^[1] Assembly plant Tochigi, Kaminokawa, Japan
13 Feb 2008	Transport Canada recall 2008050 ^[2] Issued for the model year · Airbag
6 Oct 2008	Transport Canada recall 2008363 ^[2] Issued for the model year · Other
3 Nov 2010	Transport Canada recall 2010383 ^[2] Issued for the model year · Lights and instruments
11 Feb 2015	Transport Canada recall 2015060 ^[2] Issued for the model year · Steering
25 Oct 2026	Listed for sale, Windsor, ON ^[5] Cruze Auto Sales Inc. · asking \$3,999



§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 2 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

