

Register entry, as of 27 October 2026

Listed for sale

Record ID 870fc2b01977

2007 Infiniti G35

3.5 L, 6 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JNK **BV61E** **6** **7** **M** **718032**

WMI 1-3

Infiniti · NISSAN MOTOR C...

DESCRIPTOR 4-8

G35 · 3.5 L

CHECK 9

Computes

YEAR 10

2007

PLANT 11

Tochigi

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2007	Engine	3.5 L, 6 cylinders
Make	Infiniti	Fuel	Gasoline
Model	G35	Drive	4x2
Trim	Not in the decode	Maker	NISSAN MOTOR COMPANY, LTD
Body	Sedan	Plant	Tochigi, Kaminokawa, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/infiniti/g35/2007

3 recalls listed by Transport Canada for this model year

Electrical 2010129 22 Apr 2010

On certain vehicles, the wire harness connecting the Belt Tension Sensor (BTS) and the Occupant Detection Sensor (ODS) control unit under the front passenger seat can experience relative movement, possibly caused by vehicle vibration or passenger loading on the seat cushion. The movement may cause the pin & sleeve terminals in the connector to rub against each other. This could lead to a signal interruption from the BTS to the ODS control unit. If a signal interruption is detected, the passenger airbag is designed to suppress and, if this occurred, the red supplemental airbag warning light would flash & the amber front passenger airbag status light would illuminate to alert the vehicle operator that the passenger airbag is not operating. In a crash, non-operative airbags could increase the risk of personal injury or death. Correction: Dealers will secure the Belt Tension Sensor harness connector.

Other 2008363 6 Oct 2008

On certain vehicles, a varistor in the Occupant Classification System (OCS) control unit located in the passenger seat cushion may have been manufactured incorrectly. Under certain conditions, this could cause an interruption of signal between the OCS and the Airbag control unit (ACU). This could result in the passenger airbag being suppressed. The (red) supplemental airbag warning light would flash & the (amber) front passenger airbag status light would illuminate to alert the vehicle operator, however in case of a crash a suppressed airbag could result in personal injury or death. Correction: Dealers will test the signal between the OCS & ACU and if necessary will replace the seat cushion containing OCS hardware.

Lights and instruments 2006260 11 Oct 2006

Certain vehicles fail to comply with the requirements of CMVSS 108 - Headlamp vertical gradient. Correction: Dealers will install updated headlamp assemblies.




Listed for the model year, not checked against your VIN. Infiniti confirms which apply.
Check your VIN with Infiniti Canada or call a Infiniti dealer with your VIN.
www.infiniti.ca/service/vin-recall.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$8,999^[5], the median^[4].



Same model year · 1 live listings · as of 27 Oct 2026

§4 EVENTS

2007	Model year 2007 ^[1] Assembly plant Tochigi, Kaminokawa, Japan
11 Oct 2006	Transport Canada recall 2006260 ^[2] Issued for the model year · Lights and instruments
6 Oct 2008	Transport Canada recall 2008363 ^[2] Issued for the model year · Other
22 Apr 2010	Transport Canada recall 2010129 ^[2] Issued for the model year · Electrical
24 Nov 2025	Listed for sale, Langley, BC ^[5] SJ MOTORSPORTS LTD · asking \$8,999
26 Oct 2026	Listing last updated ^[5] asking \$8,999

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

