

Register entry, as of 28 October 2026

Listed for sale

Record ID 73e140b79401

2004 Infiniti FX45

4.5 L, 8 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JNR **BS08W** **0** **4** **X** **401508**

WMI 1-3

Infiniti · NISSAN MOTOR C...

DESCRIPTOR 4-8

FX45 · 4.5 L

CHECK 9

Computes

YEAR 10

2004

PLANT 11

Samukawa

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2004	Engine	4.5 L, 8 cylinders
Make	Infiniti	Fuel	Gasoline
Model	FX45	Drive	4WD
Trim	Not in the decode	Maker	NISSAN MOTOR COMPANY, LTD
Body	Sport Utility Vehicle	Plant	Samukawa, Kanagawa, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/infiniti/fx45/2004

5 recalls listed by Transport Canada for this model year

Airbag

2020003 10 Jan 2020

Issue: This recall is for certain vehicles that had an airbag inflator replaced as a part of an earlier recall campaign. This recall provides a final repair. Long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the passenger-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function.

Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury.

Corrective Actions: Owners will be notified by mail and instructed to take their vehicle to a dealer to inspect the passenger-front airbag inflator.

The passenger-front airbag module or inflator will be replaced as necessary. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

Airbag

2016255 25 May 2016

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected. Note: This is an expansion of recall 2015210.



Lights and instruments

2006377 2 Jan 2007

Certain vehicles fail to comply with the requirements of CMVSS 108 – Lamps, Reflective Devices and Associated Equipment. The stop, tail, and turn signal lamp function may be too dim when viewed at certain angles. Reduced visibility increases the risk of the vehicle being involved in a crash. Correction: Dealers will replace the rear combination lamps.

Lights and instruments

2006194 4 Aug 2006

Certain vehicles fail to comply with the requirements of CMVSS 108 – Headlamp vertical gradient. Correction: Dealers will install new compliant headlamp assemblies.

Fuel system

2005376 29 Nov 2005

On certain vehicles, the fuel filler hose may crack from exposure to ozone. This could cause fuel leakage from the hose while refuelling and the Malfunction Indicator Light (MIL) to illuminate as a result of the onboard diagnostic system detecting a leak in the evaporative emission control system. Fuel leakage, in the presence of an ignition source, could result in a fire. Correction: Dealers will replace the fuel filler hose.

Listed for the model year, not checked against your VIN. Infiniti confirms which apply.
Check your VIN with Infiniti Canada or call a Infiniti dealer with your VIN.
www.infiniti.ca/service/vin-recall.html

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE

No priced market quote for this vehicle yet.

§4 EVENTS

2004	Model year 2004 ^[1] Assembly plant Samukawa, Kanagawa, Japan
29 Nov 2005	Transport Canada recall 2005376 ^[2] Issued for the model year · Fuel system
4 Aug 2006	Transport Canada recall 2006194 ^[2] Issued for the model year · Lights and instruments
2 Jan 2007	Transport Canada recall 2006377 ^[2] Issued for the model year · Lights and instruments
25 May 2016	Transport Canada recall 2016255 ^[2] Issued for the model year · Airbag
10 Jan 2020	Transport Canada recall 2020003 ^[2] Issued for the model year · Airbag
25 Oct 2026	Listed for sale, Vancouver, BC ^[4] 715 Motor Haus Ltd. · asking \$8,995
28 Oct 2026	Listing last updated ^[4] asking \$8,995



§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [3] NHTSA recall records (United States), listed for the model year |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

