

Register entry, as of 26 October 2026

Listed for sale

Record ID 7c2e850a87d1

2011 Suzuki Kizashi SLS (US)/SX (Canada)

2.4 L, 4 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JS2 RF9A7 X B 6 110002

WMI 1-3

Suzuki Motor Of America, Inc

DESCRIPTOR 4-8

Kizashi · 2.4 L

CHECK 9

Computes

YEAR 10

2011

PLANT 11

Sagara

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	2.4 L, 4 cylinders
Make	Suzuki	Fuel	Gasoline
Model	Kizashi	Drive	AWD
Trim	SLS (US)/SX (Canada)	Maker	SUZUKI MOTOR OF AMERICA, INC
Body	Sedan	Plant	Sagara, Kumamoto Prefecture, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/suzuki/kizashi/2011

5 recalls listed by Transport Canada for this model year

Seats and restraints

2019217 9 May 2019

Issue: On certain cars, due to the seating posture/position of the occupant, the occupant classification system (OCS) may not work properly. This could cause the airbag system to turn off the passenger-front airbag even when an adult is seated in the front passenger seat. Note: When the front passenger-front airbag is turned off, the PASS AIR BAG OFF indicator will light. Safety Risk: In a crash where an airbag is required, an airbag that does not deploy could increase the risk of injury for an adult passenger. Corrective Actions: Suzuki will mail a letter to owners to advise of this problem. A second letter will be sent once a corrective action has been determined.

Airbag

2019129 11 Mar 2019

Issue: On certain vehicles, the occupant classification system (OCS) may not work properly. This could cause the airbag system not to turn off the airbag when an infant or child is seated in the front passenger seat. This could also cause the passenger seat belt reminder to activate when the seat is empty. Note: This problem only affects vehicles with leather seats. Safety Risk: In a crash, an airbag that deploys in front of an infant or child increases the risk of injury. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a Suzuki service provider to have the front passenger seat cushion replaced.

Powertrain

2014578 18 Dec 2014

On certain vehicles, the detent pin within the shift lock structure may have been incorrectly positioned. An incorrectly positioned detent pin in combination with high temperature conditions could allow the transmission shift selector to be moved out of the PARK position without depressing the brake pedal. Depending which gear the driver selects, the vehicle could begin to move forward or backward immediately. This movement could result in property damage, or cause the vehicle to strike a bystander, potentially resulting in injury. Correction: Dealers will replace the shift selector assembly with an improved part which incorporates an extended detent pin.



Fuel system

2014320 1 Aug 2014

On certain vehicles, a particular type of spider may weave a web in the evaporative canister vent line which may cause a restriction in the line. If this occurs, the fuel tank pressure may become excessively negative when the emission control system works to purge the vapors from the canister. As the canister is purged repeatedly during normal operation, the stress on the fuel tank may eventually result in a crack causing a fuel leak. Fuel leakage, in the presence of an ignition source, could result in a fire causing injury and/or property damage. Correction: Dealers will inspect the canister vent line and replace it with a line containing a filter. If a web is found in the old line, the fuel tank will also be replaced

Other

2010212 28 Jun 2010

Certain vehicles may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 201 - Occupant Protection. The instrument panel center lower box door may not remain closed during a vehicle crash, increasing the risk of personal injury to the occupants. Correction: Dealers will replace the instrument panel center lower box with an updated version.

Listed for the model year, not checked against your VIN. Suzuki confirms which apply.


Check your VIN with Suzuki Canada or call a Suzuki dealer with your VIN.

www.suzuki.ca/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$7,495^[5], \$523 over the median of \$6,972^[4].



Lowest ask	\$6,450
Middle half	\$6,711 – \$7,234
Median ask	\$6,972
This car	\$7,495

Same model year · 2 live listings · as of 26 Oct 2026

§4 EVENTS

2011	Model year 2011 ^[1] Assembly plant Sagara, Kumamoto Prefecture, Japan
28 Jun 2010	Transport Canada recall 2010212 ^[2] Issued for the model year · Other
1 Aug 2014	Transport Canada recall 2014320 ^[2] Issued for the model year · Fuel system
18 Dec 2014	Transport Canada recall 2014578 ^[2] Issued for the model year · Powertrain
11 Mar 2019	Transport Canada recall 2019129 ^[2] Issued for the model year · Airbag
9 May 2019	Transport Canada recall 2019217 ^[2] Issued for the model year · Seats and restraints



29 Jul 2026 Listed for sale, Sutton West, ON^[5]
Unicar Auto Group · asking \$7,495

26 Oct 2026 Listing last updated^[5]
asking \$7,495

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- [1] Cardog identity register, decoded from the VIN
- [2] Transport Canada recall database, listed for the model year
- [3] NHTSA recall records (United States), listed for the model year
- [4] Cardog market quote, same model year, 2 live listings, as of 26 Oct 2026
- [5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

