

Register entry, as of 26 October 2026

Listed for sale

Record ID ffa760f811e9

2010 Suzuki SX4 Base (Canada)/Standard Sedan (US)

2.0 L, 4 cylinders · FWD · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JS2 **YA5A1** **0** **A** **6** **300033**

WMI 1-3

Suzuki Motor Of America, Inc

DESCRIPTOR 4-8

SX4 · 2.0 L

CHECK 9

Computes

YEAR 10

2010

PLANT 11

Sagara

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	2.0 L, 4 cylinders
Make	Suzuki	Fuel	Gasoline
Model	SX4	Drive	FWD
Trim	Base (Canada)/Standard Sedan (US)	Maker	SUZUKI MOTOR OF AMERICA, INC
Body	Hatchback	Plant	Sagara, Kumamoto Prefecture, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/suzuki/sx4/2010

5 recalls listed by Transport Canada for this model year

Powertrain 2014578 18 Dec 2014

On certain vehicles, the detent pin within the shift lock structure may have been incorrectly positioned. An incorrectly positioned detent pin in combination with high temperature conditions could allow the transmission shift selector to be moved out of the PARK position without depressing the brake pedal. Depending which gear the driver selects, the vehicle could begin to move forward or backward immediately. This movement could result in property damage, or cause the vehicle to strike a bystander, potentially resulting in injury. Correction: Dealers will replace the shift selector assembly with an improved part which incorporates an extended detent pin.

Airbag 2013305 17 Sep 2013

On certain vehicles, the Occupant Classification System may malfunction, causing the airbag warning lamp to illuminate, and could fail to disable the passenger airbag if a child were seated in the front passenger seating position. This could result in an unwarranted airbag deployment in a crash, increasing the risk of injury to a child seated in the front passenger seat. Note: In this situation, the "PASS AIR BAG OFF" light would fail to illuminate, regardless of if a child or adult is seated in the front passenger seat. Correction: Vehicles will receive special extended warranty coverage of 10 years or 200,000 kilometers (whichever comes first) from the date the vehicle was originally placed into service. Under this special coverage program, vehicles which experience this condition will have the occupant detection mat replaced.



Engine

2011041 27 Jan 2011

On certain vehicles, the tension adjuster pulley for the drive belt, which operates the alternator, water pump, air conditioner compressor and power steering pump, may contain an improperly manufactured internal spring that can break due to repeated stress. Should the spring break, this would cause the drive belt tension to be maladjusted, allowing the belt to slip. If the belt comes off, the loss of steering power assist would require the driver to exert increased effort to steer the vehicle. This could result in a crash causing property damage and/or personal injury. Additionally, the loss of water pump function would cause the coolant temperature to rise, which can lead to engine overheating, while the loss of alternator charging ability would lead to battery discharge and eventual engine stall. Correction: Dealers will replace the drive belt tension adjuster pulley.

Visual system

2010363 22 Oct 2010

On certain vehicles, the three (3) screws that secure the outside rearview mirrors to the base may come loose due to vibration and, in worst case, the mirror may separate from the vehicle. Absence of rearview mirror(s) increases the risk of a crash. Correction: Dealers will replace existing screws with Thread-Lock pre-coated screws.

Label

2010293 3 Sep 2010

On certain vehicles, the Tire & Vehicle Loading Placard (Label) may depict an incorrect tire size. Correction: Dealers will install revised placards over the original placard for all existing and incoming inventory. Retail customers will receive a letter which will include a revised label and instructions on how to install it. Owners will also have the option of having their Dealer install the label for them.

Listed for the model year, not checked against your VIN. Suzuki confirms which apply.

Check your VIN with Suzuki Canada or call a Suzuki dealer with your VIN.

www.suzuki.ca/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$6,767^[5], \$64 under the median of \$6,831^[4].



Lowest ask	\$6,767
Middle half	\$6,799 – \$6,863
Median ask	\$6,831
This car	\$6,767

Same model year · 2 live listings · as of 26 Oct 2026

OTHER 2010 SUZUKI SX4 LISTINGS ^[5]

North Vancouver, BC · 176,215 km \$6,895

§4 EVENTS

2010 **Model year 2010**^[1]
Assembly plant Sagara, Kumamoto Prefecture, Japan

3 Sep 2010 **Transport Canada recall 2010293**^[2]
Issued for the model year · Label

22 Oct 2010 **Transport Canada recall 2010363**^[2]
Issued for the model year · Visual system



27 Jan 2011	Transport Canada recall 2011041 ^[2] Issued for the model year · Engine
17 Sep 2013	Transport Canada recall 2013305 ^[2] Issued for the model year · Airbag
18 Dec 2014	Transport Canada recall 2014578 ^[2] Issued for the model year · Powertrain
22 Aug 2026	Listed for sale, St Catharines, ON ^[5] 5 Stars Motors · asking \$6,767
26 Oct 2026	Listing last updated ^[5] asking \$6,767

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 2 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 26 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

