

Register entry, as of 26 October 2026

Listed for sale

Record ID 461fc329b51d

2007 Suzuki Grand Vitara Premium Plus Package (JLX)

2.7 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JS3

WMI 1-3

Suzuki Motor Of America, Inc

TD945

DESCRIPTOR 4-8

Grand Vitara · 2.7 L

3

CHECK 9

Computes

7

YEAR 10

2007

4

PLANT 11

Iwata

200290

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2007	Engine	2.7 L, 6 cylinders
Make	Suzuki	Fuel	Gasoline
Model	Grand Vitara	Drive	4WD
Trim	Premium Plus Package (JLX)	Maker	SUZUKI MOTOR OF AMERICA, INC
Body	Sport Utility Vehicle	Plant	Iwata, Shizuoka, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/suzuki/grand-vitara/2007

4 recalls listed by Transport Canada for this model year

Airbag 2019129 11 Mar 2019

Issue: On certain vehicles, the occupant classification system (OCS) may not work properly. This could cause the airbag system not to turn off the airbag when an infant or child is seated in the front passenger seat. This could also cause the passenger seat belt reminder to activate when the seat is empty. Note: This problem only affects vehicles with leather seats. Safety Risk: In a crash, an airbag that deploys in front of an infant or child increases the risk of injury. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a Suzuki service provider to have the front passenger seat cushion replaced.

Steering 2018549 5 Oct 2018

On certain vehicles, the tension adjuster pulley for the drive belt which operates the power steering pump and air conditioner compressor (if equipped) has an outer portion that is made of plastic. Repeated heat stress can cause the plastic material to deteriorate and pieces of the pulley can break off. Broken pieces of the pulley can get caught between the pulley and the drive belt, causing the drive belt to come off and resulting in the driver needing increased effort to steer the vehicle. This situation could result in a crash causing property damage, personal injury or death. Correction: Dealers will replace the power steering pump drive belt tension adjuster pulley. Note: This is an expansion of recall 2010-197.



Airbag

2013305 17 Sep 2013

On certain vehicles, the Occupant Classification System may malfunction, causing the airbag warning lamp to illuminate, and could fail to disable the passenger airbag if a child were seated in the front passenger seating position. This could result in an unwarranted airbag deployment in a crash, increasing the risk of injury to a child seated in the front passenger seat. Note: In this situation, the "PASS AIR BAG OFF" light would fail to illuminate, regardless of if a child or adult is seated in the front passenger seat. Correction: Vehicles will receive special extended warranty coverage of 10 years or 200,000 kilometers (whichever comes first) from the date the vehicle was originally placed into service. Under this special coverage program, vehicles which experience this condition will have the occupant detection mat replaced.

Other

2007391 6 Dec 2007

On certain vehicles, the ignition/park shift interlock system may become inoperable. This can allow the shifter to be moved out of the PARK position with the ignition key removed. This could allow the vehicle to roll away, possibly causing property damage and/or personal injury or death. Correction: Dealers will replace the shift lock module on the shift lever assembly.

Listed for the model year, not checked against your VIN. Suzuki confirms which apply.
Check your VIN with Suzuki Canada or call a Suzuki dealer with your VIN.

www.suzuki.ca/recalls/

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$1,500^[5], \$7,395 under the median of \$8,895^[4].



Lowest ask	\$8,895
Middle half	\$5,198 – \$8,945
Median ask	\$8,895
This car	\$1,500

Same model year · 3 live listings · as of 26 Oct 2026

OTHER 2007 SUZUKI GRAND VITARA LISTINGS ^[5]

North Vancouver, BC · 189,042 km	\$8,895
London, ON · 135,995 km	\$8,995

§4 EVENTS

2007	Model year 2007 ^[1] Assembly plant Iwata, Shizuoka, Japan
6 Dec 2007	Transport Canada recall 2007391 ^[2] Issued for the model year · Other
17 Sep 2013	Transport Canada recall 2013305 ^[2] Issued for the model year · Airbag
5 Oct 2018	Transport Canada recall 2018549 ^[2] Issued for the model year · Steering
11 Mar 2019	Transport Canada recall 2019129 ^[2] Issued for the model year · Airbag



24 Oct 2026 Listed for sale, Kingston, ON^[5]
Kingston Volkswagen Audi · asking \$1,500

26 Oct 2026 Listing last updated^[5]
asking \$1,500

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 3 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 26 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

