

Register entry, as of 28 October 2026

Listed for sale

Record ID c901b73a17a1

2002 Toyota Camry

3.0 L, 6 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTD BF30K 8 2 0 039688

WMI 1-3

Toyota Motor Corporation

DESCRIPTOR 4-8

Camry · 3.0 L

CHECK 9

Computes

YEAR 10

2002

PLANT 11

Japan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2002	Engine	3.0 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	Camry	Drive	4x2
Trim	Not in the decode	Maker	TOYOTA MOTOR CORPORATION
Body	Sedan	Plant	Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/camry/2002

3 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Airbag

2004240 12 Jul 2004

On certain vehicles equipped with the Curtain Shield airbag system, the curtain airbag may be twisted near the inflator due to improper assembly. In this condition, the gas supplied by the inflator may be inadequate for proper inflation of the bag, causing incomplete inflation of the curtain in the event of a collision. Correction: Dealers will inspect, and replace the curtain airbag if necessary.

Airbag

2001282 5 Dec 2001

Certain passenger vehicles equipped with a three-spoke style steering wheel. During air bag deployment, it is possible that the bottom seam of the front driver's side air bag module cover (horn pad) could be torn away allowing the bottom portion of the cover to completely detach from the air bag module. If this should occur, there is a possibility that the detached bottom portion may strike the driver causing personal injury. Correction: dealers will replace the driver's side air bag module.




Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$5,995^[5], the median^[4].



Lowest ask	\$5,995
Middle half	\$5,995 – \$5,995
Median ask	\$5,995
This car	\$5,995

Same model year · 1 live listings · as of 28 Oct 2026

§4 EVENTS

2002	Model year 2002 ^[1] Assembly plant Japan
5 Dec 2001	Transport Canada recall 2001282 ^[2] Issued for the model year · Airbag
12 Jul 2004	Transport Canada recall 2004240 ^[2] Issued for the model year · Airbag
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
26 Oct 2026	Listed for sale, McMasterville, QC ^[5] Paradis Auto · asking \$5,995
27 Oct 2026	Listing last updated ^[5] asking \$5,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 28 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

