

Register entry, as of 29 October 2026

Listed for sale

Record ID 08164f0e93a6

2018 Toyota Prius Two Eco/Three/Three Touring/Four/Four Touring

1.8 L, 4 cylinders · 4x2 · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTD **KARFU** **7** **J** **3** **554351**

WMI 1-3

Toyota Motor Corporation

DESCRIPTOR 4-8

Prius · 1.8 L

CHECK 9

Computes

YEAR 10

2018

PLANT 11

Toyota City

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	1.8 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	Prius	Drive	4x2
Trim	Two Eco/Three/Three Touring/Four/Four Touring	Maker	TOYOTA MOTOR CORPORATION
Body	Hatchback	Plant	Toyota City, Aichi, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/prius/2018

3 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Electrical

2019434 28 Aug 2019

Issue: On certain vehicles, a connection in the main wire harness may have been damaged during assembly. This could cause hybrid drive system to shut down, and result in a loss of power to the drive wheels. If this happens, an error message will display on the instrument panel and a warning chime will sound. Note: This recall only affects vehicles which had the seat heater installed at the port facility. Safety Risk: A loss of power to the drive wheels could increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and instruct them to take their vehicle to a dealer to repair the wire connections.



Electrical

2018477 5 Sep 2018

On certain vehicles, the hybrid vehicle Power Control Unit connector cover could come into contact with the wiring harness and could cause wear on the wiring insulation. If bare wires become exposed, an electrical short circuit could occur, which could increase the risk of fire causing injury and/or damage to property. Correction: Dealers will inspect the wiring for damage and, as necessary, install protective tape or replace the wire harness assembly with a new one, which includes a protective sleeve.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$22,516^[5], \$1,518 over the median of \$20,998^[4].



Lowest ask	\$13,999
Middle half	\$17,277 – \$22,516
Median ask	\$20,998
This car	\$22,516

Same model year · 5 live listings · as of 29 Oct 2026

OTHER 2018 TOYOTA PRIUS LISTINGS [5]

St-Eustache, QC · 126,612 km	\$17,277
New Westminster, BC · 114,708 km	\$20,998
Victoria, BC · 93,040 km	\$23,400
Milton, ON · 84,340 km	\$22,995
Halton Hills, ON · 214,529 km	\$13,999

§4 EVENTS

2018	Model year 2018 ^[1] Assembly plant Toyota City, Aichi, Japan
5 Sep 2018	Transport Canada recall 2018477 ^[2] Issued for the model year · Electrical
28 Aug 2019	Transport Canada recall 2019434 ^[2] Issued for the model year · Electrical
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
25 Oct 2026	Listed for sale, Peterborough, ON ^[5] Holiday Ford Lincoln · asking \$22,516
29 Oct 2026	Listing last updated ^[5] asking \$22,516



§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 5 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

