

Register entry, as of 27 October 2026

Listed for sale

Record ID ac145d0d2320

2015 Toyota Prius V

1.8 L, 4 cylinders · 4x2 · Wagon · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTD **ZN3EU** **6** **F** **J** **027731**

WMI 1-3

Toyota Motor Corporation

DESCRIPTOR 4-8

Prius V · 1.8 L

CHECK 9

Computes

YEAR 10

2015

PLANT 11

Toyota City

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	1.8 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	Prius V	Drive	4x2
Trim	Not in the decode	Maker	TOYOTA MOTOR CORPORATION
Body	Wagon	Plant	Toyota City, Aichi, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/prius-v/2015

3 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Electrical

2020284 25 Jun 2020

Issue: The Intelligent Power Module (IPM), which is part of the hybrid drive system, could become damaged under certain driving conditions. This could cause various warnings to appear on the instrument panel and cause the hybrid system to shut down. If this happens, there can be a loss of power to the wheels. Safety Risk: A loss of power to the wheels could create the risk of a crash. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to update the software for the hybrid system.



Airbag

2015014 15 Jan 2015


Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 208 – Occupant Protection. The passenger seat occupant classification system (OCS) may have been calibrated incorrectly during the manufacturing process. This could result in the non-deployment of an airbag, which would increase the risk of injury to the seat occupant in a crash where airbag deployment is warranted. Correction: Dealers will reprogram the occupant classification system (OCS).

Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$18,999^[5], \$1,049 over the median of \$17,950^[4].



Lowest ask	\$16,900
Middle half	\$17,425 – \$18,474
Median ask	\$17,950
This car	\$18,999

Same model year · 2 live listings · as of 27 Oct 2026

OTHER 2015 TOYOTA PRIUS V LISTINGS ^[5]

Chilliwack, BC · 276,265 km \$16,900

§4 EVENTS

2015	Model year 2015 ^[1] Assembly plant Toyota City, Aichi, Japan
15 Jan 2015	Transport Canada recall 2015014 ^[2] Issued for the model year · Airbag
25 Jun 2020	Transport Canada recall 2020284 ^[2] Issued for the model year · Electrical
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
6 Oct 2026	Listed for sale, Coquitlam, BC ^[5] Blue Jay Auto Sales · asking \$18,999
27 Oct 2026	Listing last updated ^[5] asking \$18,999



§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 2 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

