Register entry, as of 24 November 2026 Not listed for sale Record ID 5e8c9322bfea

2021 Toyota Venza

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTE	AAAAH	5	M	J	068298
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Corporation	Venza · 2.5 L	Computes	2021	Toyota City	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.5 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	Venza	Drive	4WD
Trim	Not in the decode	Maker	TOYOTA MOTOR CORPORATION
Body	Sport Utility Vehicle	Plant	Toyota City, Aichi, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/venza/2021

2 recalls listed by Transport Canada for this model year

Brakes

2022179 13 Apr 2022

Issue: Under certain conditions, the vehicle stability control (VSC) system may not switch on when the ignition is restarted. This can happen if the driver manually turns off the VSC, depresses the brake pedal, and then turns off and restarts the vehicle while continuously depressing the brake pedal. Canadian regulations require the stability control system to be active each time that you start the vehicle. Safety Risk: A stability control system that is switched off could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to update the skid control ECU software.

Lights and instruments

2022021 26 Jan 2022

Issue: On certain vehicles, the rear turn signal bulbs could short circuit. If this happens, the turn signals and hazard lights may dim or may not work properly. Note: This problem can cause the turn signal indicator on the instrument panel to flash quickly. Safety Risk: Turn signals that do not work properly could cause a following driver not to recognize that a vehicle ahead intends to turn. Hazard lights that do not work properly could make the vehicle less visible. This could increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and instruct you to bring your vehicle to a dealer to replace both rear turn signal bulbs. The dealer will also replace the rear turn signal lamp assemblies, if necessary.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

Median ask $29,995[4] for same configuration.



Lowest ask	$27,999
Middle half	$29,920 – $32,660
Median ask	$29,995

Same configuration · 14 live listings · as of 23 Nov 2026

OTHER 2021 TOYOTA VENZA LISTINGS [5]

Ottawa, ON · 102,000 km	$29,995
Courtenay, BC · 54,236 km	$37,998
Ajax, ON · 124,384 km	$29,999
Toronto, ON · 110,202 km	$29,895
Brossard, QC · 23,500 km	$36,995
Edmundston, NB · 149,829 km	$29,995

§4 EVENTS

2021	Model year 2021[1] Assembly plant Toyota City, Aichi, Japan
26 Jan 2022	Transport Canada recall 2022021[2] Issued for the model year · Lights and instruments
13 Apr 2022	Transport Canada recall 2022179[2] Issued for the model year · Brakes

Not in a live public dealer listing on Cardog as of 24 Nov 2026.[5]

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 14 live listings, as of 23 Nov 2026
[5] Live public dealer listings on Cardog, as of 24 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.