

Register entry, as of 27 October 2026

Listed for sale

Record ID 1a2bc5479d93

2010 Toyota FJ Cruiser GSJ15L/GSJ10L

4.0 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTE **BU4BF** **8** **A** **K** **089193**

WMI 1-3

Toyota Motor Corporation

DESCRIPTOR 4-8

FJ Cruiser · 4.0 L

CHECK 9

Computes

YEAR 10

2010

PLANT 11

Hamura

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	4.0 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	FJ Cruiser	Drive	4WD
Trim	GSJ15L/GSJ10L	Maker	TOYOTA MOTOR CORPORATION
Body	Sport Utility Vehicle	Plant	Hamura, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/fj-cruiser/2010

3 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Seats and restraints

2013084 15 Mar 2013

On certain vehicles, due to insufficient strength of the access door (rear door) panels, cracks may develop if the access doors are repeatedly and forcefully closed over an extended period of time. As the driver and front passenger seat belt retractors are mounted in the access door panels, if cracks occur in the panel around the lower retractor anchor, the seat belt retractors could become detached. This could increase the risk of injury to an occupant in the event of a crash. Correction: Dealers will inspect the rear door panels for cracks or separation. Depending on the results of the inspection, the dealer will repair as necessary.



Label

2011104 4 Mar 2011


Certain vehicles fail to conform to Canada Motor Vehicle Safety Standard 110 – Tire Selection and Rims. These vehicles may have been equipped with accessory alloy wheels and tires prior to delivery to the customer. The specifications and recommended tire inflation pressures for the original equipment wheel and tire sizes, and the accessory wheel and tire size, are different. A replacement tire loading placard may not have been provided when the accessory wheels and tires were installed. Correction: Dealers will install a replacement tire loading placard.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$25,005^[5], \$7,005 over the median of \$18,000^[4].



Lowest ask	\$10,995
Middle half	\$14,498 – \$21,502
Median ask	\$18,000
This car	\$25,005

Same model year · 2 live listings · as of 27 Oct 2026

OTHER 2010 TOYOTA FJ CRUISER LISTINGS [5]

Toronto, ON · 327,416 km \$10,995

§4 EVENTS

2010	Model year 2010 ^[1] Assembly plant Hamura, Japan
4 Mar 2011	Transport Canada recall 2011104 ^[2] Issued for the model year · Label
15 Mar 2013	Transport Canada recall 2013084 ^[2] Issued for the model year · Seats and restraints
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
14 Oct 2026	Listed for sale, Grande Prairie, AB ^[5] Grande Prairie Hyundai · asking \$25,005
26 Oct 2026	Listing last updated ^[5] asking \$25,005



§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 2 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

